



report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	Blue
Year of manufacture	2010
Top speed	142 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-22
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-20
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #13	2023-10-20 07:23
MOT test number	574947942647
Result	✓ Passed
Next expiry date	2024-10-20

MOT #12	2022-09-22 08:14
MOT test number	702613674385
Result	✓ Passed

MOT #11	2022-09-22 08:14
MOT test number	500157722513
Result	✗ Failed
<b>Pass with rectification</b> Nearside Headlamp aim too high (4.1.2 (a))	

MOT #10	2021-10-14 07:40
MOT test number	920564537069
Result	✓ Passed

MOT #9	2020-10-19 14:51
MOT test number	416885383541
Result	✓ Passed

**MOT #8**

2019-10-14 07:27

**MOT test number**

881941991183

**Result**

✓ Passed

**Advice**

Exhaust has a minor leak of exhaust gases from rear exhaust box (6.1.2 (a))

**Minor**

Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Front top o2 sensor wiring is damage

**Advice**

Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. 30% imbalance on front (1.2.1 (b) (i))

**Advice**

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7**

2018-10-17 13:24

**MOT test number**

559459484959

**Result**

✓ Passed

**Advice**

Nearside Rear tyre cut, cracking on tread and edge perished, 205/45 R 17

**Advice**

Offside Rear cracking on tread and edge perished

**MOT #6**

2017-10-18 10:53

**MOT test number**

982816148212

**Result**

✓ Passed

**Advice**

Nearside Front TYRE WORN EDGES 205/45/17V

**Advice**

Rear SILENCER SMALL LEAK

**Advice**

Offside Front TYRE WORN EDGES

**Advice**

Offside Front Brake pad(s) wearing thin 70% WORN (3.5.1g)



<b>MOT #5</b>	2016-10-11 07:59
---------------	------------------

<b>MOT test number</b>	666432973190
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Rear Tyre has a cut but does not expose cords or threads.
---------------	---

<b>MOT #4</b>	2015-10-19 08:47
---------------	------------------

<b>MOT test number</b>	636458469078
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2014-10-07 11:37
---------------	------------------

<b>MOT test number</b>	436190484265
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-10-21 14:21
---------------	------------------

<b>MOT test number</b>	417644093226
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-12-06 10:56
---------------	------------------

<b>MOT test number</b>	487461942469
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2024

✓  
**MOT**  
  
Expires:  
20 October 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	20 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 <b>KS60ZKR</b>
Plate since	2019-09-29
Current registration	 <b>KS60ZKR</b>
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-28
Last registration	2023-10-20
Complete history	<a href="#">See info</a>



Registration #1	2010-09-28	23 mi
Registration #2	2012-12-06	13.840 mi
Registration #3	2013-10-21	17.489 mi
Registration #4	2014-10-07	19.749 mi
Registration #5	2015-10-19	24.952 mi
Registration #6	2016-10-11	27.276 mi
Registration #7	2017-10-18	32.955 mi
Registration #8	2018-10-17	41.839 mi
Registration #9	2019-10-17	50.723 mi
Registration #10	2020-10-17	59.607 mi
Registration #11	2021-10-17	68.491 mi
Registration #12	2022-10-17	77.375 mi
Registration #13	2023-10-17	86.259 mi
Registration #14	2024-03-28	95.143 mi
Registration #15	2024-03-28	104.027 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	A7111774