

Ford



# General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	159 g/km
CO2 label	G



## MOT history

MOT expiry date	2024-11-19
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	36
Total items failed	15

MOT #17	2023-11-07 14:52
MOT test number	488135188101
Result	✓ Passed
Next expiry date	2024-11-19
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

## MOT #16

## 2022-10-20 10:57

435152750185

#### **MOT test number**

 Result
 Passed

 Advice
 Rear Brake pipe corroded, covered in grease or other material both rear starting to bubble under plastic cover (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Brake pipe corroded, covered in grease or other material both rear starting to bubble under plastic cover (1.1.11 (c))

MOT #15	2021-11-20 13:51
MOT test number	980416287618
Result	✓ Passed



MOT #14		2020-11-20 15:57
MOT test	number	225565836493
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2020-11-20 12:14
MOT test number	101108841679
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Bonnet cannot be secured in the closed position (3.1 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12		2019-10-15 14:30
MOT test	number	145020433952
Result		✓ Passed
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	





report date: 2024-03-28

MOT #11	2019-10-15 08:32
MOT test number	752951850107
Result	🗙 Failed
<b>Fail</b> Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail         Offside Registration plate lamp inoperative in the case of a single lamp or all land	nps (4.7.1 (b) (ii))
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
<b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail         Nearside Registration plate lamp inoperative in the case of a single lamp or all la	amps (4.7.1 (b) (ii))
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail         Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #10		2018-10-19 13:48
MOT test	number	297506442089
Result		🗸 Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2018-10-19 09:10
MOT test number	390656054318
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Pass with rectification</b> Nearside Headlamp aim too high (4.1.2 (a))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Fail</b> Exhaust has a major leak of exhaust gases centre section (6.1.2 (a))	





MOT #8	2017-10-19 07:25
MOT test number	749157298688
Result	✓ Passed
MOT #7	2017-10-05 09:22
MOT test number	196783226446
Result	🗙 Failed
Fail         Indicator tell tale inoperative (1.4.A.2a)	
FailSpeedometer clearly inoperative (6.7.2)	
Fail         Main beam 'tell-tale' not working (1.7.4c)	
Fail         Rear fog lamp tell tale not working (1.3.1b)	

МОТ #6	2016-10-05 11:17
MOT test number	390045133736
Result	✓ Passed
Advice Offside Rear Nail in tyre	

MOT #5	2016-10-04 12:58
MOT test number	215004706461
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre has ply or cords exposed depth 1.6 mm (4.1.D.1b)	
Advice N/s/f tyre is worn smooth on the inner edge	
Advice Offside Rear Nail in tyre	
Advice Nearside Front Tyre worn close to the legal limit 2.0 mm (4.1.E.1)	

MOT #4	2015-09-28 13:03
MOT test number	368473133662
Result	✓ Passed





MOT #3		2014-10-02 14:04
MOT test	number	477475074267
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Passenger seat(s) missing at time of test	

MOT #2	2013-10-10 14:55
MOT test number	436473683224
Result	✓ Passed
<b>Notice</b> Passenger seat(s) missing at time of test	

MOT #1	2012-10-08 14:42
MOT test number	557932482225
Result	✓ Passed
<b>Notice</b> O/s front tyre wall has slight cracking	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 19 November 2024
Tax status	Valid until 1 October
Days left	156
MOT expiry date	19 November 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrient registration	
Current registration Pate since	
Carrent registration Fate since Carrent registration	
Carrent registration Foto since Foto since Foto since	8000-20-20





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-27
Last registration	2023-11-07
Complete history	See info



Registration #1	2009-11-27	26 mi
Registration #2	2012-10-08	36.275 mi
Registration #3	2013-10-10	51.607 mi
Registration #4	2014-10-02	65.759 mi
Registration #5	2015-09-28	82.907 mi
Registration #6	2016-10-04	75.877 mi
Registration #7	2016-10-05	95.902 mi
Registration #8	2017-10-05	109.139 mi
Registration #9	2017-10-19	109.252 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi
Registration #18		11.117 esi





## Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles	2
Engine number	9K79070