





report date: 2024-03-29

General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 308 S/S ALLURE |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 125 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history


Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-03-08 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 5 |

| MOT #7 | 2024-03-05 09:16 |
|--|-------------------------|
| MOT test number | 824734921617 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-08 |
| Advice Offside Front Anti-roll bar linkage ball joint has slight | ht play (5.3.4 (a) (i)) |
| Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a |) (ii)) |
| Advice Both front tyres wearing low on inner edges | |

| MOT #6 | 2023-02-25 09:04 |
|---|------------------|
| MOT test number | 941303760920 |
| Result | ✓ Passed |
| Advice Items removed from driver's view prior to test | |

| MOT #5 | 2022-03-07 09:58 |
|-----------------|------------------|
| MOT test number | 961070109964 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

| MOT #4 | 2022-03-05 15:52 |
|---|------------------|
| MOT test number | 832714030734 |
| Result | × Failed |
| Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #3 | 2021-03-09 14:35 |
|--|------------------|
| MOT test number | 275373633391 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2020-07-21 16:18 |
| MOT test number | 361356018638 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-07-21 07:45 |
| MOT test number | 483364543044 |
| Result | × Failed |
| Advice Front Brake disc worn, but not excessively both fronts (1.1.14 (a) (i)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Rear Brake disc worn, but not excessively both rears (1.1.14 (a) (i)) | |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 305 |
| MOT expiry date | 8 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Vehicle valuation

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



ober of plates

faste since

WV67RWO

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0 | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-09-07 |
| Last registration | 2024-03-05 |
| Complete history | See info |



| Registration #1 | 2017-09-07 | 26 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-07-21 | 23.220 mi |
| Registration #3 | 2020-07-21 | 23.222 mi |
| Registration #4 | | 71.777 66 |
| Registration #5 | 2021-03-09 | 24.402 mi |
| Registration #6 | | 71.777 66 |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 ea |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 79% |
| Pedestrian | 64% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1804 mm |
|---------------------|---------|
| Height | 1457 mm |
| Length | 4253 mm |
| Wheel base | 2620 mm |
| Kerb weight | 1150 kg |
| Max. allowed weight | 1750 kg |

Additional information

| Fuel tank capacity | 53 l |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number XTA10515224