



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Red
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-26
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	9
Total items failed	12

MOT #12	2023-07-27 09:06
MOT test number	319053912524
Result	✓ Passed
Next expiry date	2024-07-29
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #11	2022-07-20 16:24
MOT test number	283215519677
Result	✓ Passed

**MOT #10**

2022-07-20 10:09

MOT test number

367429661460

Result**✗ Failed**

- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Parking brake inoperative on one side low (1.4.1 (a))

MOT #9

2021-07-30 14:47

MOT test number

872426332898

Result**✓ Passed****MOT #8**

2021-07-27 14:23

MOT test number

689220909438

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7

2020-09-03 10:36

MOT test number

844281079830

Result**✓ Passed**

- Advice** Coil spring corroded x4 (5.3.1 (b) (i))

**MOT #6** 2019-05-22 13:50**MOT test number** 320434929822**Result** ✓ Passed**MOT #5** 2019-05-21 08:57**MOT test number** 393587609549**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #4** 2018-05-21 09:55**MOT test number** 325554603364**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-05-19 10:32**MOT test number** 863716503243**Result** ✓ Passed**MOT #2** 2017-05-16 15:45**MOT test number** 931846841725**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Inner Drive shaft which forms part of the suspension coupling gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.4.G.4e)



MOT #1	2016-05-20 14:35
MOT test number	148538662872
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-05-31
Last registration	2023-07-27
Complete history	See info



Registration #1	2013-05-31	19 mi
Registration #2	2016-05-20	44.136 mi
Registration #3	2017-05-16	57.289 mi
Registration #4	2017-05-19	57.289 mi
Registration #5	2018-05-21	72.546 mi
Registration #6	2019-05-21	82.368 mi
Registration #7	2019-05-22	82.372 mi
Registration #8	2019-05-22	82.372 mi
Registration #9	2019-05-22	82.372 mi
Registration #10	2019-05-22	82.372 mi
Registration #11	2019-05-22	82.372 mi
Registration #12	2019-05-22	82.372 mi
Registration #13	2019-05-22	82.372 mi
Registration #14	2019-05-22	82.372 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1802 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1390 kg
Max. allowed weight	1890 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	2353086
---------------	---------