





report date: 2024-03-29

#### General information

Make	FIAT
Model	PUNTO MULTIJET DYNAMIC
Colour	Red
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-08-08

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2023-03-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #11	2022-03-17 11:54
MOT test number	941913597383
Result	✓ Passed
Next expiry date	2023-03-20

MOT #10		2021-03-17 12:06
MOT test	number	519370460944
Result		✓ Passed
Advice	Nearside Rear Shock absorber corroded	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Exhaust silencer corroded / deteriorated	

MOT #9	2020-03-21 14:01
MOT test number	190076994944
Result	✓ Passed
Advice Front and rear suspension components have slight surface rust and corr	rosion
Minor Stop lamp(s) lens defective which has no effect on emitted light both rear sides (4.3.1 (b) (i))	
Advice Exhaust corroded	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

688666876858

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Brake pad(s) wearing thin front pads very thin marginal pass (1.1.13 (a) (ii))

Advice Rear heat shield loose

**MOT** #7 2019-03-12 08:53 **MOT** test number 599569330874 Result × Failed **Advice** Rear heat shield loose Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure 195/55/16 (5.2.3 (d) (ii)) **Advice** Brake pad(s) wearing thin front pads appear thin (1.1.13 (a) (ii))

MOT #6

MOT test number

Result

Advice Engine warning light and general warning lights on

2018-03-14 15:33

353178428661

✓ Passed

CarCheck.co.uk page 4/12



**Advice** 

CV61NWY

report date: 2024-03-29

**MOT #5** 2018-03-12 08:47 **MOT** test number 668906889916 Result × Failed Fail Nearside Headlamp aim too low (1.8) **Advice** Offside Rear Tyre worn close to the legal limit on legal limit (4.1.E.1) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm also out of shape (4.1.E.1) Offside Front coil spring broken (2.4.C.1a) Fail **Advice** Engine warning light and general warning lights on

 MOT #4
 2017-03-07 15:38

 MOT test number
 918463458325

 Result
 ✓ Passed

MOT test number

Result

Offside Front Inner Front constant velocity joint is insecure clip loose (2.5.C.1b)

Fail Nearside Front Inner Front constant velocity joint is insecure clip loose (2.5.C.1b)

 MOT #2
 2016-03-19 10:04

 MOT test number
 815833303071

 Result
 ✓ Passed

 MOT #1
 2015-02-02 09:44

 MOT test number
 119123335013

 Result
 ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 5/12



CV61NWY
report date: 2024-03-29

Tax & MOT check



Tax expired: 11 October 2022

# X MOT

Expired: 20 March 2023

Tax status	Expired at 11 October 2022
Days left	566 days too late
MOT expiry date	20 March 2023
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-30
Last registration	2022-03-17
Complete history	See info



Registration #1	2012-01-30	22 mi
Registration #2	2015-02-02	36.086 mi
Registration #3	2016-03-19	45.444 mi
Registration #4	2017-03-07	58.611 mi
Registration #5	2017-03-07	58.614 mi
Registration #6	2018-03-12	68.858 mi
Registration #7	2018-03-14	68.894 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 11/12



CV61NWY
report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1090 kg
Max. allowed weight	1650 kg

# Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

**Engine number** 4066955