



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE EU4
Colour	Silver
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





MOT history

MOT expiry date	2023-12-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	7

MOT #17 2023-12-20 14:49

MOT test number 583970692551

Result ✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement FRONT BUSH (5.3.4 (a) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** UNDER TRAYS / SILL COVERS FITTED
- Advice** Front Registration plate deteriorated but not likely to be misread DAMAGED (0.1 (b))
- Advice** Oil leak, but not excessive ENGINE (8.4.1 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement FRONT BUSH (5.3.4 (a) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2022-12-13 17:01

MOT test number

737539770947

Result

✓ Passed

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #15**

2021-12-09 10:49

MOT test number

519467771458

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2020-11-09 16:18

MOT test number

924479289109

Result

✓ Passed

MOT #13

2019-05-31 14:36

MOT test number

612377286321

Result

✓ Passed

Minor Offside Headlamp lens slightly defective lens deteriorated (4.1.1 (b) (i))

**MOT #12** 2019-05-22 09:33**MOT test number** 165240921631**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Minor** Offside Headlamp lens slightly defective lens deteriorated (4.1.1 (b) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #11** 2018-06-05 14:18**MOT test number** 296061679837**Result** ✓ Passed**MOT #10** 2017-06-05 16:20**MOT test number** 681658381633**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement front (2.4.G.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2016-07-18 10:37**MOT test number** 409393861340**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #8** 2015-08-11 16:03**MOT test number** 495372391476**Result** ✓ Passed**MOT #7** 2014-08-27 16:53**MOT test number** 108159434272**Result** ✓ Passed**MOT #6** 2013-10-14 13:14**MOT test number** 575887283229**Result** ✓ Passed**MOT #5** 2012-10-12 10:08**MOT test number** 857756882288**Result** ✓ Passed**MOT #4** 2011-10-19 15:29**MOT test number** 408002191265**Result** ✓ Passed



MOT #3	2010-10-18 11:35
MOT test number	152951490215
Result	✓ Passed
<div>Notice</div> Middle exhaust bracket broken at one side,but exhaust still supported	

MOT #2	2009-10-28 11:00
MOT test number	233421009372
Result	✓ Passed

MOT #1	2009-10-27 13:00
MOT test number	931110509382
Result	✗ Failed
<div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<div>Fail</div> Offside Front Track rod end ball joint has excessive play (2.2.B.1f)	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
12 December 2023

Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SV56WXC
Plate since	2024-03-29
Current registration	SV56WXC
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-11-15
Last registration	2023-12-20
Complete history	See info



Registration #1	2006-11-15	7 mi
Registration #2	2009-10-27	25.928 mi
Registration #3	2009-10-28	25.928 mi
Registration #4	2010-10-18	31.567 mi
Registration #5	2011-10-19	37.096 mi
Registration #6	2012-10-12	42.646 mi
Registration #7	2013-10-14	48.660 mi
Registration #8	2014-08-27	55.480 mi
Registration #9	2015-08-11	63.820 mi
Registration #10	2016-08-11	71.277 mi
Registration #11	2017-08-11	78.734 mi
Registration #12	2018-08-11	86.191 mi
Registration #13	2019-08-11	93.648 mi
Registration #14	2020-08-11	101.105 mi
Registration #15	2021-08-11	108.562 mi
Registration #16	2022-08-11	116.019 mi
Registration #17	2023-08-11	123.476 mi
Registration #18	2023-12-20	126.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	363695