



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC DESIGN
Colour	Bronze
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	147 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



Internet history

Entry 1

Date	2021-11-20
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-16
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	3
Total items failed	6

MOT #9	2024-03-16 09:58
MOT test number	236535242123
Result	✓ Passed
Next expiry date	2025-03-16

MOT #8	2023-03-17 14:43
MOT test number	416469566571
Result	✓ Passed

MOT #7	2023-03-17 12:27
MOT test number	546467731313
Result	✗ Failed

- Fail** Offside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #6	2022-02-23 18:04
MOT test number	304906286769
Result	✓ Passed

**MOT #5** 2021-08-10 14:00**MOT test number** 838086875449**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing also both fronts (5.2.3 (d) (ii))**MOT #4** 2021-08-09 16:00**MOT test number** 809762516730**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing also both fronts (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #3** 2020-09-15 11:32**MOT test number** 970403369162**Result** ✓ Passed**MOT #2** 2020-09-15 08:21**MOT test number** 749790739146**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 215/55/17 (5.2.3 (e))**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #1** 2019-09-09 14:33**MOT test number** 679652004258**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 March 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	AF66KUA
Plate since	2024-03-29
Current registration	AF66KUA
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-16
Last registration	2024-03-16
Complete history	See info



Registration #1	2016-09-16	11 mi
Registration #2	2019-09-09	28.587 mi
Registration #3	2020-09-15	42.467 mi
Registration #4	2020-09-15	42.467 mi
Registration #5	2021-08-09	54.041 mi
Registration #6	2021-08-10	54.041 mi
Registration #7	2022-03-22	55.277 mi
Registration #8	2022-03-22	55.277 mi
Registration #9	2022-03-22	55.277 mi
Registration #10	2022-03-22	55.277 mi
Registration #11	2024-03-16	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Engine number

2ZRV405495