



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV CDTi (150)
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-01
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-10
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	18
Total items failed	1

MOT #18	2023-03-06 10:44
MOT test number	671782805648
Result	✓ Passed
Next expiry date	2024-03-10

MOT #17	2023-03-04 09:16
MOT test number	564437182396
Result	✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16** 2022-03-05 10:01**MOT test number** 171904134343**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake pads low**MOT #15** 2021-03-09 10:32**MOT test number** 970782111842**Result** ✓ Passed**Advice** Front Coil spring corroded O/S,N/S (5.3.1 (b) (i))**MOT #14** 2020-03-05 12:07**MOT test number** 920995787503**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-03-05 11:27**MOT test number** 748075549584**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure cut (5.2.3 (d) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2019-03-08 11:05**MOT test number** 136794178976**Result** ✓ Passed

**MOT #11** 2019-03-08 10:29**MOT test number** 169578132631**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2018-03-06 12:25**MOT test number** 237529288631**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-03-09 10:26**MOT test number** 877937756858**Result** ✓ Passed**MOT #8** 2016-03-08 09:33**MOT test number** 767814661620**Result** ✓ Passed**MOT #7** 2015-03-05 15:49**MOT test number** 977634165022**Result** ✓ Passed**MOT #6** 2014-03-10 12:42**MOT test number** 945349764074**Result** ✓ Passed**Notice** Front & rear not able to see inner brake pad wear.**MOT #5** 2013-03-11 16:52**MOT test number** 876680473085**Result** ✓ Passed



<b>MOT #4</b>	2013-03-11 10:59
---------------	------------------

<b>MOT test number</b>	958460273055
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Offside Front coil spring incomplete (2.4.C.1a)
-------------	---

<b>MOT #3</b>	2012-02-24 11:56
---------------	------------------

<b>MOT test number</b>	818155152008
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2011-02-28 11:53
---------------	------------------

<b>MOT test number</b>	776259551092
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-03-03 14:51
---------------	------------------

<b>MOT test number</b>	304632360065
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:  
15 December 2023

X

MOT

Expired:  
10 March 2024

Tax status	Expired at 15 December 2023
Days left	135 days too late
MOT expiry date	10 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BU07YKB
Plate since	2019-09-29
Current registration	 BU07YKB
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-30
Last registration	2023-03-06
Complete history	<a href="#">See info</a>



Registration #1	2007-03-30	16 mi
Registration #2	2010-03-03	31.420 mi
Registration #3	2011-02-28	40.994 mi
Registration #4	2012-02-24	49.503 mi
Registration #5	2013-03-11	57.927 mi
Registration #6	2013-03-11	52.929 mi
Registration #7	2014-03-10	64.393 mi
Registration #8	2015-03-05	67.666 mi
Registration #9	2016-03-08	69.354 mi
Registration #10	2017-03-09	70.613 mi
Registration #11	2018-03-10	71.977 mi
Registration #12	2019-03-11	73.341 mi
Registration #13	2020-03-12	74.705 mi
Registration #14	2021-03-13	76.069 mi
Registration #15	2022-03-14	77.433 mi
Registration #16	2023-03-15	78.797 mi
Registration #17	2024-03-16	80.161 mi
Registration #18	2025-03-17	81.525 mi
Registration #19	2026-03-18	82.889 mi
Registration #20	2027-03-19	84.253 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1798 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1456 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17224973