



report date: 2024-03-29

General information

Make	MINI
Model	UNKNOWN COOPER S
Colour	Silver
Year of manufacture	2015
Top speed	142 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	192 BHP
Max. torque	280 Nm at 4.600 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 3

Date	2022-01-15
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 2

Date	2021-10-10
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-10-09
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-28
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	22
Total items failed	0

MOT #8	2024-02-29 13:01
--------	------------------

MOT test number	848529568632
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-28
------------------	------------

- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Under tray fitted not allowing full inspection
- Advice** Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7**

2024-02-16 10:10

**MOT test number**

757062462618

**Result****✗ Failed****Advice** Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**DANGEROUS** Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Under tray fitted not allowing full inspection**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Nearside Front Inner Road wheel fractured has a crack (5.2.2 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**MOT #6**

2023-02-22 13:30

**MOT test number**

822181597083

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5**

2022-01-31 15:11

**MOT test number**

103446994651

**Result****✓ Passed****MOT #4**

2022-01-21 09:57

**MOT test number**

357090371159

**Result****✗ Failed****MAJOR** Nearside Front Brake hose excessively chafed (1.1.12 (b) (ii))



MOT #3	2020-11-18 14:03
MOT test number	871647667589
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge Both (inner edges) (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MOT #2	2019-11-20 11:49
MOT test number	902195891918
Result	✓ Passed
Minor	Horn not working properly (7.7 (a) (i))

MOT #1	2018-10-29 14:54
MOT test number	828467033070
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
28 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	28 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-29
Current registration	
Plate since	2019-06-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-27
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2015-11-27	23 mi
Registration #2	2018-10-29	21.336 mi
Registration #3	2019-11-20	29.518 mi
Registration #4	2020-11-18	39.230 mi
Registration #5	2020-11-20	39.230 mi
Registration #6	2020-11-20	39.230 mi
Registration #7	2020-11-20	39.230 mi
Registration #8	2020-11-20	39.230 mi
Registration #9	2020-11-20	39.230 mi
Registration #10	2020-11-20	39.230 mi
Registration #11	2020-11-20	39.230 mi
Registration #12	2020-11-20	39.230 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2022 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1435 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	F5161270
---------------	----------