



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | VOLKSWAGEN |
| Model | SCIROCCO GT TDI |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 138 mph |
| 0 - 60 mph | 8.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 130 kW / 177 HP / 175 BHP |
| Max. torque | 350 Nm at 1.750 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-09-25 |
| Pictures | 32 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-24 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-29 |
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 18 |
| Total items failed | 5 |

| | |
|------------------|---|
| MOT #11 | 2023-09-23 09:29 |
| MOT test number | 571741481831 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-29 |
| Minor | Tyre obviously under inflated all (5.2.3 (I)) |

| | |
|-------------------------|--|
| MOT #10 | 2023-09-23 09:29 |
| MOT test number | 298455374887 |
| Result | ✗ Failed |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |
| Minor | Tyre obviously under inflated all (5.2.3 (I)) |

| | |
|-----------------|--|
| MOT #9 | 2022-09-24 10:56 |
| MOT test number | 525963004710 |
| Result | ✓ Passed |
| Advice | Windscreen chipped |
| Minor | Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #8 | 2021-09-24 16:09 |
| MOT test number | 550776138884 |
| Result | ✓ Passed |

**MOT #7** 2021-09-24 13:41**MOT test number** 381259630371**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #6** 2020-09-30 11:30**MOT test number** 235375267082**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** Vehicle emissions to clean**MOT #5** 2020-09-28 10:53**MOT test number** 189578613242**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 235/35/19 pirelli p zero (5.2.3 (d) (ii))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Nail in tyre**Advice** Vehicle emissions to clean**MOT #4** 2019-05-08 14:49**MOT test number** 976936802440**Result** ✓ Passed**Advice** Vehicle emissions to clean**Advice** Nearside Rear Nail in tyre

**MOT #3** 2019-05-08 10:44**MOT test number** 384133344876**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure x2 235/35/19 pirelli p zero (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Vehicle emissions to clean**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #2** 2018-04-28 15:55**MOT test number** 851631843915**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Advise engine management light on dash.**Advice** Offside Rear Nail in tyre**MOT #1** 2017-05-09 08:09**MOT test number** 402274682904**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 338 |
| MOT expiry date | 29 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  LL14NTT |
| Plate since | 2019-06-29 |
| Current registration |  LL14NTT |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2014-05-10 |
| Last registration | 2023-09-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-05-10 | 24 mi |
| Registration #2 | 2017-05-09 | 32.054 mi |
| Registration #3 | 2018-04-28 | 43.905 mi |
| Registration #4 | 2019-05-08 | 54.917 mi |
| Registration #5 | 2019-05-08 | 54.917 mi |
| Registration #6 | 2020-09-28 | 68.130 mi |
| Registration #7 | 2020-09-30 | 68.172 mi |
| Registration #8 | 2020-09-30 | 68.172 mi |
| Registration #9 | 2020-09-30 | 68.172 mi |
| Registration #10 | 2020-09-30 | 68.172 mi |
| Registration #11 | 2020-09-30 | 68.172 mi |
| Registration #12 | 2020-09-30 | 68.172 mi |
| Registration #13 | 2020-09-30 | 68.172 mi |
| Registration #14 | 2020-09-30 | 68.172 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1404 mm |
| Length | 4256 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1274 kg |
| Max. allowed weight | 1760 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of axles | 2 |

