



General information

| | |
|---------------------|------------------------|
| Make | AUDI |
| Model | A3 TFSI SE |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 138 mph |
| 0 - 60 mph | 7.7 seconds |
| Gearbox | 7 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 158 BHP |
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 31.4 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-27 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-14 |
| MOT pass rate | 82 % |
| MOT passed | 14 |
| Failed MOT tests | 3 |
| Total advice items | 43 |
| Total items failed | 0 |

| | |
|------------------|------------------------------------------------------------------------|
| MOT #17 | 2024-02-15 10:18 |
| MOT test number | 283735230344 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-14 |
| Advice | Front Registration plate insecure but not likely to fall off (0.1 (a)) |

| | |
|-----------------|--------------------------------------------------------------------------------------------------|
| MOT #16 | 2024-02-14 12:49 |
| MOT test number | 232603406765 |
| Result | ✗ Failed |
| DANGEROUS | Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Advice | Front Registration plate insecure but not likely to fall off (0.1 (a)) |
| MAJOR | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) |
| MAJOR | Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Minor | Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i)) |
| MAJOR | Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| MAJOR | Front Service brake excessively fluctuating (1.2.1 (e)) |
| MAJOR | Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |
| MAJOR | Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| MAJOR | Nearside Rear Service brake excessively binding (1.2.1 (f)) |

**MOT #15**

2022-10-25 09:23

MOT test number

960038091042

Result

✓ Passed

Advice Vehicles internal headlight adjuster altered to recheck lights**Advice** Fuel cap seal cracked but seals**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14**

2022-10-17 10:05

MOT test number

679393756285

Result

✗ Failed

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MAJOR** Central Rear Seat belt buckle damaged (7.1.2 (d))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Fuel cap seal cracked but seals**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #13**

2021-09-08 11:43

MOT test number

181340546484

Result

✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge both and slight perishing (5.2.3 (e))

**MOT #12**

2021-09-08 09:54

MOT test number

476475104554

Result**✗ Failed**

DANGEROUS Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge both and slight perishing (5.2.3 (e))

MOT #11

2020-12-23 10:28

MOT test number

599346055088

Result**✓ Passed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-12-20 10:55

MOT test number

482741019387

Result**✓ Passed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Obligatory mirror slightly loose (3.3 (b) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2018-12-18 10:47**MOT test number** 417049153325**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #8** 2017-12-09 11:46**MOT test number** 350395651742**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2016-11-01 11:51**MOT test number** 453810015748**Result** ✓ Passed**MOT #6** 2015-11-06 14:19**MOT test number** 840265902282**Result** ✓ Passed**MOT #5** 2015-05-08 14:47**MOT test number** 199968925161**Result** ✓ Passed**MOT #4** 2014-06-13 11:55**MOT test number** 466984664175**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #3 | 2014-04-16 12:03 |
| MOT test number | 218176404412 |
| Result | ✓ Passed |
| MOT #2 | 2014-03-19 11:14 |
| MOT test number | 375518574045 |
| Result | ✓ Passed |
| MOT #1 | 2013-04-22 12:44 |
| MOT test number | 516582413151 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 14 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 48 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |
| Current registration | XXXXXX |
| Plate since | 2019-01-01 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2010-04-28 |
| Last registration | 2024-02-15 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-04-28 | 9 mi |
| Registration #2 | 2013-04-22 | 22.971 mi |
| Registration #3 | 2014-03-19 | 29.695 mi |
| Registration #4 | 2014-04-16 | 30.182 mi |
| Registration #5 | 2014-06-13 | 31.172 mi |
| Registration #6 | 2015-05-08 | 35.147 mi |
| Registration #7 | 2015-11-06 | 41.116 mi |
| Registration #8 | 2016-11-01 | 47.661 mi |
| Registration #9 | 2017-12-09 | 57.577 mi |
| Registration #10 | 2018-12-18 | 64.895 mi |
| Registration #11 | 2019-01-01 | 65.000 mi |
| Registration #12 | 2019-01-01 | 65.000 mi |
| Registration #13 | 2019-01-01 | 65.000 mi |
| Registration #14 | 2019-01-01 | 65.000 mi |
| Registration #15 | 2019-01-01 | 65.000 mi |
| Registration #16 | 2019-01-01 | 65.000 mi |
| Registration #17 | 2019-01-01 | 65.000 mi |
| Registration #18 | 2019-01-01 | 65.000 mi |
| Registration #19 | 2019-01-01 | 65.000 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1765 mm |
| Height | 1423 mm |
| Length | 4292 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1335 kg |
| Max. allowed weight | 1895 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|------------|
| Number of axles | 2 |
| Engine number | CDA 081383 |