



report date: 2024-03-28

General information

Make	MAZDA
Model	2 SPORT
Colour	Grey
Year of manufacture	2011
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	133 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	3

MOT #13 2024-01-10 13:50

MOT test number 968461961743

Result ✓ Passed

Next expiry date 2025-01-13

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Upper Macpherson strut mounting damaged but not seriously weakened Noisy (5.3.3 (b) (i))
- Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

MOT #12 2023-01-14 09:42

MOT test number 519660870228

Result ✓ Passed

MOT #11 2021-12-11 12:34

MOT test number 439540817605

Result ✓ Passed

**MOT #10** 2020-09-04 10:21**MOT test number** 162000980367**Result** ✓ Passed**MOT #9** 2020-09-03 11:45**MOT test number** 623822830376**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #8** 2019-09-20 10:39**MOT test number** 602612000238**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #7** 2019-09-20 10:29**MOT test number** 200610772047**Result** ✗ Failed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #6** 2018-09-19 14:55**MOT test number** 451769586193**Result** ✓ Passed**MOT #5** 2017-09-16 09:29**MOT test number** 177425117393**Result** ✓ Passed

**MOT #4** 2017-09-16 09:29**MOT test number** 199652507053**Result** ✗ Failed**Pass with rectification** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2016-09-08 14:13**MOT test number** 319212884204**Result** ✓ Passed**Advice** Front knocking noise sensation from steering colum**MOT #2** 2015-09-04 09:12**MOT test number** 510112916158**Result** ✓ Passed**Advice** Steering system slightly rough (2.2.D.1)**Advice** Exhaust slightly corroded**Advice** Nearside Rear tyre perrished**Advice** Noise on steering**MOT #1** 2014-09-01 10:40**MOT test number** 229744544283**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-27
Last registration	2024-01-10
Complete history	See info



Registration #1	2011-09-27	23 mi
Registration #2	2014-09-01	17.646 mi
Registration #3	2015-09-04	21.569 mi
Registration #4	2016-09-08	28.312 mi
Registration #5	2017-09-16	34.503 mi
Registration #6	2017-09-16	34.503 mi
Registration #7	2018-09-19	39.799 mi
Registration #8	2019-09-20	46.587 mi
Registration #9	2020-09-20	53.377 mi
Registration #10	2021-09-20	60.167 mi
Registration #11	2022-09-20	66.957 mi
Registration #12	2023-09-20	73.747 mi
Registration #13	2024-01-10	80.537 mi
Registration #14	2024-01-10	80.537 mi
Registration #15	2024-01-10	80.537 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZY 723650