



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





MOT history

MOT expiry date	2023-06-12
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	37
Total items failed	14

MOT #16	2022-06-13 15:04
MOT test number	662256384482
Result	✓ Passed
Next expiry date	2023-06-12
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15	2020-11-28 09:10
MOT test number	672092644271
Result	✓ Passed
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear fuel cap cover missing
Advice	Offside Front Seat belt buckle slightly damaged cover missing (7.1.2 (d))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #14**

2019-12-30 10:01

MOT test number

935414626372

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Valve stem slightly damaged Both. (5.2.3 (j))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing Both. (5.2.3 (d) (ii))**MOT #13**

2019-01-09 12:35

MOT test number

941590154914

Result

✓ Passed

Advice Offside Front Seat belt buckle slightly damaged Plastic casing missing. (7.1.2 (d))**MOT #12**

2019-01-09 12:35

MOT test number

730616535714

Result

✗ Failed

Advice Offside Front Seat belt buckle slightly damaged Plastic casing missing. (7.1.2 (d))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11**

2018-01-19 16:04

MOT test number

162413902851

Result

✓ Passed

Advice Both front tyres wearing smooth outer edges**Advice** Seat belt attachment fitting slightly deteriorated buckle (5.2.3)**Advice** Slight smear front wipers**Advice** Front Front suspension has slight movement at a wishbone pin or bush both sides (2.5.A.1c)

**MOT #10**

2018-01-19 13:23

MOT test number

414830591887

Result**✗ Failed****Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Slight smear front wipers**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Front Front suspension has slight movement at a wishbone pin or bush both sides (2.5.A.1c)**Advice** Seat belt attachment fitting slightly deteriorated buckle (5.2.3)**Advice** Both front tyres wearing smooth outer edges**MOT #9**

2017-01-24 10:59

MOT test number

142255640647

Result**✓ Passed****Advice** O/S/F seat belt buckle casing broken. Seat belt meets requirements at time of test.**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear most bush (2.4.G.2)**Advice** Fuel filler cap outer flap missing**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear most bush. (2.4.G.2)**Advice** N/S/F tyre worn smooth on inner edge. Would advise replacement.**MOT #8**

2016-01-27 12:05

MOT test number

393337175908

Result**✓ Passed****Advice** Child seat fitted o/s/r not allowing full test of adult seat belt**Advice** Both rear tyres perished, cracked, worn out of shape and low on tread.**Advice** O/s/f seat belt buckle casing missing

**MOT #7** 2015-01-14 17:05**MOT test number** 835704315002**Result** ✓ Passed**MOT #6** 2015-01-09 12:51**MOT test number** 267589305032**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a)**Notice** O/s/r tyre perished and has minor cuts and damage to its tread pattern**Notice** N/s/f tyre worn on inner edge and in very poor condition**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Shock absorber has slight external damage to the casing (2.7.2a)**Notice** N/s/r tyre perished and has minor cuts and damage to its tread pattern**Notice** O/s/f tyre wearing on inner edge**Fail** Headlamp switch faulty (1.7.1)**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2014-01-15 15:14**MOT test number** 726535114046**Result** ✓ Passed

**MOT #4** 2014-01-13 15:44**MOT test number** 595833714085**Result** ✗ Failed

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Horn not working (1.6.2a)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3 2013-01-09 11:12**MOT test number** 176409103438**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2013-01-07 18:52**MOT test number** 776497903017**Result** ✗ Failed

- Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)
- Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Offside Rear wheel bearing rough when rotated (2.6.1)
- Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)

MOT #1 2011-12-22 15:22**MOT test number** 325856151316**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
12 June 2023

Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YH58UTG
Plate since	2019-03-29
Current registration	 YH58UTG
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-12-30
Last registration	2022-06-13
Complete history	See info



Registration #1	2008-12-30	23 mi
Registration #2	2011-12-22	39.432 mi
Registration #3	2013-01-07	48.867 mi
Registration #4	2013-01-09	48.867 mi
Registration #5	2014-01-13	57.710 mi
Registration #6	2014-01-15	57.716 mi
Registration #7	2015-01-09	66.074 mi
Registration #8	2015-01-14	66.084 mi
Registration #9	2016-01-27	73.970 mi
Registration #10	2016-01-27	73.970 mi
Registration #11	2016-01-27	73.970 mi
Registration #12	2016-01-27	73.970 mi
Registration #13	2016-01-27	73.970 mi
Registration #14	2016-01-27	73.970 mi
Registration #15	2016-01-27	73.970 mi
Registration #16	2016-01-27	73.970 mi
Registration #17	2016-01-27	73.970 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BUD524379