



report date: 2024-03-28

General information

Make	VAUXHALL
Model	CASCADA SE CDTI S/S
Colour	Brown
Year of manufacture	-
Top speed	135 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	165 BHP
Max. torque	350 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-02-05
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

Entry 1

Date	2021-01-22
Pictures	20
Listing price	<a href="#">View report</a>



source: yesauto.com

**MOT history**

<b>MOT #10</b>	2023-09-27 13:26
<b>MOT test number</b>	980504402084
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-26

<b>MOT #9</b>	2023-09-27 13:26
<b>MOT test number</b>	701269006030
<b>Result</b>	✗ Failed
<b>Pass with rectification</b> Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

<b>MOT #8</b>	2023-03-28 12:37
<b>MOT test number</b>	905382703179
<b>Result</b>	✓ Passed
<b>Advice</b> Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

<b>MOT #7</b>	2023-03-28 12:37
<b>MOT test number</b>	269436593317
<b>Result</b>	✗ Failed
<b>Advice</b> Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Pass with rectification</b> Windscreen washer not working (3.5 (a))	

<b>MOT #6</b>	2022-03-29 13:00
<b>MOT test number</b>	917725982653
<b>Result</b>	✓ Passed
<b>Minor</b> Front Windscreen wiper blade defective (3.4 (b) (i))	
<b>Advice</b> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #5** 2021-03-15 16:58**MOT test number** 301008506623**Result** ✓ Passed**MOT #4** 2020-04-03 08:48**MOT test number** 264078909580**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2019-03-28 10:44**MOT test number** 478750837382**Result** ✓ Passed**MOT #2** 2018-03-29 07:45**MOT test number** 460508532106**Result** ✓ Passed**MOT #1** 2017-05-12 08:58**MOT test number** 332367634696**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	HV14WDA
Plate since	2019-06-29
Current registration	HV14WDA
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-23
Last registration	2023-09-27
Complete history	<a href="#">See info</a>



Registration #1	2014-05-23	7 mi
Registration #2	2017-05-12	21.342 mi
Registration #3	2018-03-29	24.246 mi
Registration #4	2019-03-28	28.408 mi
Registration #5	2020-04-03	38.390 mi
Registration #6	2020-05-20	39.377 mi
Registration #7	2020-05-20	39.377 mi
Registration #8	2020-05-20	39.377 mi
Registration #9	2020-05-20	39.377 mi
Registration #10	2020-05-20	39.377 mi
Registration #11	2020-05-20	39.377 mi
Registration #12	2020-05-20	39.377 mi
Registration #13	2020-05-20	39.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	87%
Children	72%
Pedestrian	65%
Safety systems	81%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2020 mm
Height	1443 mm
Length	4696 mm
Wheel base	2695 mm
Kerb weight	1741 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	A20DTH -17A95920LBS