



General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Red
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-29
Pictures	33
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	36
Total items failed	7

MOT #24 2024-04-09 16:33**MOT test number** 800133295937**Result** ✓ Passed**Next expiry date** 2025-04-08**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))**MOT #23** 2024-04-08 14:49**MOT test number** 297179288898**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #22** 2023-04-25 09:51**MOT test number** 159899821547**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust system corroded

**MOT #21** 2022-05-16 14:10**MOT test number** 870499440186**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Slight cracking in tread pattern. (5.2.3 (d) (ii))

Advice Nearside Front Vehicle structure is deformed but structural rigidity is not significantly reduced Chassic extension slightly deformed. (6.1.1 (a) (i))

MOT #20 2022-05-16 11:07**MOT test number** 900675488445**Result** ✗ Failed

MAJOR Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

Advice Nearside Front Vehicle structure is deformed but structural rigidity is not significantly reduced Chassic extension slightly deformed. (6.1.1 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Slight cracking in tread pattern. (5.2.3 (d) (ii))

MAJOR Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

MOT #19 2021-05-19 15:43**MOT test number** 359374645486**Result** ✓ Passed**MOT #18** 2021-01-21 14:47**MOT test number** 405751808239**Result** ✓ Passed

**MOT #17**

2021-01-20 09:56

MOT test number

284619430609

Result**✗ Failed****DANGEROUS** Offside Front Valve stem seriously damaged (5.2.3 (j))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Steering rack has excessive free play detected at the steering wheel (steering rack fitted)
track rod (2.3 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #16**

2020-01-11 09:01

MOT test number

463229989749

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #15**

2019-01-16 11:57

MOT test number

533430060080

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2019-01-16 10:37**MOT test number** 101609784152**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MAJOR** Stop lamp(s) not working high level (4.3.1 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**MOT #13** 2018-01-16 10:36**MOT test number** 738780113598**Result** ✓ Passed**Advice** Offside Front tyre worn to 2mm tread**MOT #12** 2018-01-16 10:36**MOT test number** 266504407886**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front tyre worn to 2mm tread**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #11** 2017-01-18 10:47**MOT test number** 501511812262**Result** ✓ Passed

**MOT #10** 2017-01-18 10:47**MOT test number** 306714384527**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #9** 2016-01-15 10:03**MOT test number** 934886273279**Result** ✓ Passed**MOT #8** 2015-01-16 12:16**MOT test number** 438656815057**Result** ✓ Passed**MOT #7** 2015-01-15 15:01**MOT test number** 628675415026**Result** ✗ Failed**Fail** Offside Front front brake excessively fluctuating (3.7.B.3)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #6** 2013-11-12 09:24**MOT test number** 737216413332**Result** ✓ Passed**Notice** Rear tyres perishing**MOT #5** 2012-11-21 12:18**MOT test number** 977996422320**Result** ✓ Passed

**MOT #4** 2012-07-04 10:27**MOT test number** 568666182107**Result** ✓ Passed**MOT #3** 2012-07-04 10:27**MOT test number** 476566482192**Result** ✗ Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Pass with rectification Centre Stop lamp not working (1.2.1b)

MOT #2 2011-07-28 10:34**MOT test number** 867649701237**Result** ✓ Passed

Notice Nail in offside rear tyre

MOT #1 2010-09-01 10:02**MOT test number** 130744740248**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
8 April 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	GV57NNG
Plate since	2019-03-28
Current registration	GV57NNG
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-10-26
Last registration	2024-04-09
Complete history	See info



Registration #1	2007-10-26	25 mi
Registration #2	2010-09-01	11.335 mi
Registration #3	2011-07-28	13.816 mi
Registration #4	2012-07-04	26.632 mi
Registration #5	2012-11-21	17.534 mi
Registration #6	2013-11-12	23.910 mi
Registration #7	2015-01-15	26.785 mi
Registration #8	2015-01-16	26.785 mi
Registration #9	2016-01-15	28.516 mi
Registration #10	2017-01-18	29.820 mi
Registration #11	2017-01-18	29.820 mi
Registration #12	2018-01-15	31.131 mi
Registration #13	2018-01-15	31.131 mi
Registration #14	2018-01-15	31.131 mi
Registration #15	2018-01-15	31.131 mi
Registration #16	2018-01-15	31.131 mi
Registration #17	2018-01-15	31.131 mi
Registration #18	2018-01-15	31.131 mi
Registration #19	2018-01-15	31.131 mi
Registration #20	2018-01-15	31.131 mi
Registration #21	2018-01-15	31.131 mi
Registration #22	2018-01-15	31.131 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7E54776