





General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Silver
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D







Internet history		
Entry 1		
Date	2021-02-06	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk



MOT history

MOT expiry date	2024-04-04
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	9

MOT #7	2023-04-05 15:40
MOT test number	834963070202
Result	✓ Passed
Next expiry date	2024-04-04
Minor Offside Obligatory mirror slightly damaged Incorrect mirror fitted (3.3 (b) (i)))

MOT #6	2023-04-05 08:37
MOT test number	606443179578
Result	🗙 Failed
Fail Offside Front Outer Tyre has a cut in excess of the requirements deep enough to cords (5.2.3 (d) (i))	reach the ply or
Fail Offside Rear Outer Tyre has a bulge, caused by separation or partial failure of its (ii))	structure (5.2.3 (d)
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
Fail Front Windscreen washer provides insufficient washer liquid Unable to check wipe	ers (3.5 (a))
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))	





MOT #5	2	022-04-05 08:07
MOT test	number	344254123518
Result		🗸 Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Tyre worn close to legal limit/worn on edge both sides inner tread (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	4 2022	-03-29 08:33
MOT te	st number 78	34885345017
Result		🗙 Failed
Fail	Offside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))	
Fail	Rear Registration plate does not conform to the specified requirements (0.1 (d))	
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Front Registration plate does not conform to the specified requirements (0.1 (d))	

MOT #3	2021-03-03 15:01
MOT test number	827958261811
Result	✓ Passed

MOT #2		2020-02-19 13:26
MOT test	number	278372346314
Result		✓ Passed
Advice	Both rear tyres wearing out of shape	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #1		2019-02-20 11:28
MOT test	number	253356332123
Result		Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Both rear tyres tread wearing out of shape	



KN16FFP report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 1 February 2024	X MOT Expired: 4 April 2024
Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	4 April 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-17
Last registration	2023-04-05
Complete history	See info



Registration #1	2016-03-17	11 mi
Registration #2	2019-02-20	18.550 mi
Registration #3	2020-02-19	23.320 mi
Registration #4		11.117 esi
Registration #5	2021-03-03	23.535 mi
Registration #6		11.117 esi
Registration #7		11.177 mi
Registration #8		11.177 esi
Registration #9		11.777 esi

More info >






Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight	
Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1457 kg
Max. allowed weight	1965 kg
Additional information	
Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	1632610