





report date: 2024-03-29

### General information

Make	FORD
Model	C-MAX TITANIUM 115
Colour	Black
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	115 BHP
Max. torque	280 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg



CarCheck.co.uk page 1/11




## Internet history


#### Entry 1


Date 2021-08-28

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT #14	2022-07-21 07:54
MOT test number	502828979101
Result	<b>✓</b> Passed
Next expiry date	2023-07-20
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #13		2022-07-21 07:54
MOT test number		441451237779
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Exhaust m	ounting defective (6.1.2 (a))	

MOT #12	2021-06-28 16:54
MOT test number	926359281236
Result	✓ Passed

MOT #11	2020-07-16 09:35
MOT test number	447693207305
Result	✓ Passed

MOT #10	2020-07-15 16:24
MOT test number	426530236476
Result	<b>★</b> Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #9	2019-05-23 10:47
MOT test number	560509191925
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



Result

YF09WRJ report date: 2024-03-29

✓ Passed

MOT #8 2018-06-12 09:38

**MOT test number** 780706436908

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-06-06 11:11

**MOT test number** 766729311640

Result × Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Nail in tyre

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



**MOT test number** 

YF09WRJ report date: 2024-03-29

251929334705

MOT #6 2017-06-05 08:	
MOT #6 2017-06-05 08:	27

MOT #5 2016-06-13 10:42

**MOT test number** 768525128912

**Result** ✓ Passed

MOT #4 2015-06-10 10:00

**MOT test number** 245311365440

Result \( \sqrt{Passed} \)

MOT #3 2014-06-26 10:09

**MOT test number** 277657674427

MOT #2 2013-06-14 10:25

**MOT test number** 497405863183

Result \( \sqrt{Passed} \)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-06-06 16:41

**MOT test number** 877978152165

**Result** ✓ Passed

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union motory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
***************************************	
	More info >
Plate changes  See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-07-02
Last registration	2022-07-21
Complete history	See info



Registration #1	2009-07-02	26 mi
Registration #2	2012-06-06	22.827 mi
Registration #3	2013-06-14	34.736 mi
Registration #4	2014-06-26	45.590 mi
Registration #5	2015-06-10	58.010 mi
Registration #6	2016-06-13	71.836 mi
Registration #7	2017-06-05	84.082 mi
Registration #8	2018-06-06	94.189 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1512 kg
Max. allowed weight	1995 kg

## Additional information

Fuel tank capacity	53 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number9J36113