





General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	Grey
Year of manufacture	2011
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	61.4 mpg



Internet history

Entry 2

Date Pictures 2022-01-18

14

Listing price

View report



source: yesauto.com

Entry 1

Date

Pictures

Listing price

2022-01-16

15

View report



source: cargurus.co.uk









MOT history

MOT expiry date	2024-08-08
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #11	2023-08-09 07:41
MOT test number	555445554147
Result	✓ Passed
Next expiry date	2024-08-08
Advice Exhaust outer cover corroded	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #10		2023-08-03 09:58
MOT test	number	872989477982
Result		🗙 Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Exhaust outer cover corroded	

MOT #9	2022-01-19 17:20
MOT test number	850432736736
Result	✓ Passed





MOT #8	2021-01-07 10:35
MOT test number	643373607937
Result	✓ Passed
MOT #7	2020-01-07 14:35
MOT test number	524825373700
Result	✓ Passed
MOT #6	2018-11-09 11:25

MOT test number	173296116684
Result	✓ Passed

MOT #5	2018-11-05 13:12
MOT test number	340149608788
Result	🗙 Failed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #4		2017-10-10 14:33
MOT test	number	609323675838
Result		✓ Passed
Advice	Handbrake travel high	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nail in osr tyre tread	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	



FG61FBN report date: 2024-03-29

MOT #3		2016-09-06 09:53
MOT test	number	253342358238
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Windscreen has damage to an area less than a 10mm circle withi	n zone 'A' (8.3.1a)
NOT #2		2015 02 22 17 22
MOT #2		2015-02-23 17:33
MOT test	number	478564255095
Result		✓ Passed

MOT #1	2014-09-25 12:	49
MOT test	number 3665382644	56
Result	✓ Pass	ed
Advice	Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)	



Tax & MOT check







Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



FG61FBN report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-30
Last registration	2023-08-09
Complete history	See info



Registration #1	2011-09-30	24 mi
Registration #2	2014-09-25	43.857 mi
Registration #3	2015-02-23	43.967 mi
Registration #4	2016-09-06	59.378 mi
Registration #5	2017-10-10	65.830 mi
Registration #6	2018-11-05	75.383 mi
Registration #7	2018-11-09	75.438 mi
Registration #8		11.117 esi
Registration #9		10.207 mi
Registration #9 Registration #10		00.000 est
-		01.000 est 01.000 est 01.000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est



Car features

S0225	Air conditionin
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1321 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	45
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982964254