





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	T-ROC R-LINE TDI
Colour	Black
Year of manufacture	2019
Top speed	124 mph
0 - 100 km/h	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	50.4 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2023-06-03

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-01-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-16
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #4	2024-01-04 11:08
MOT test number	155370648005
Result	✓ Passed
Next expiry date	2025-01-16
Minor Offside Windscreen damaged but not adversely affecting driver's v	riew minor (3.2 (a) (i))

MOT #3		2023-01-16 16:55
MOT test	number	493238160574
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2	2022-01-17 08:14
MOT test number	288408234744
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view small stone chip in zone A (3.2 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-01-12 12:26 **MOT test number** 278394901113 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Minor Windscreen damaged but not adversely affecting driver's view small stone chip in zone A (3.2 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



WD19VSO report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-05-22
Last registration	2024-01-04
Complete history	See info



Registration #1	2019-05-22	11 mi
Registration #2	2022-01-12	23.446 mi
Registration #3	2022-01-17	23.446 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	87%
Pedestrian	79%
Safety systems	71%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1819 mm
Height	1573 mm
Length	4234 mm
Wheel base	2 mm
Kerb weight	1315 kg
Max. allowed weight	1920 kg

Additional information

Number of seats	5	
Number of axles	2	
Engine number	DFFA287577	
CarChack coluk		nage 11/11

CarCheck.co.uk page 11/11