





General information	
Make	RENAULT
Model	MEGANE SCENIC DYNAMIQUE DCI 130 G/SCENIC
Colour	Grey
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	300 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg



Internet history

Entry 1

Date Pictures 2022-01-17

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #20	2022-06-23 15:31
MOT test number	209312325364
Result	✓ Passed
Next expiry date	2023-06-22
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #19	2022-06-20 11:59
MOT test number	415740983700
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ing	gress of dirt (5.3.4 (b) (ii))
Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #18	2021-06-23 10:43
MOT test number	951281543329
Result	✓ Passed
Advice Nearside Front Play in steering rack inner joint(s)	





MOT #17	2021-06-16 10:20
MOT test number	246492148592
Result	🗙 Failed
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Play in steering rack inner joint(s)	
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #16		2020-06-22 09:46
MOT test	number	482737039645
Result		🗸 Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Play in steering rack inner joint(s)	

MOT #15		2019-06-17 09:38
MOT test	number	705850567957
Result		✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Child Seat fitted not allowing full inspection of adult belt	

MOT #14		2019-06-17 09:38
MOT test number		794605651847
Result		× Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))	
Advice Nearside Front Play in steering rack inner joint(s)		
Advice Child Seat fitted	not allowing full inspection of adult belt	



MOT #13		2018-06-18 15:06
MOT test num	ber	456056037534
Result		✓ Passed
Advice Nea	rside Play in steering rack inner joint(s)	
Advice Offs	ide Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nea	rside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #12		2018-06-18 11:44
MOT test num	ber	912646698973

 Result
 X Failed

 Fail
 Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

 Advice
 Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))


 Advice
 Nearside Play in steering rack inner joint(s)

 Fail
 Offside Stop lamp(s) not working (4.3.1 (a) (ii))

 Fail
 Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

2017-06-12 13:46
578857658506
✓ Passed

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Advice

YJ06ROU

report date: 2024-03-29



YJO6ROU report date: 2024-03-29

MOT #10	2017-06-12 11:27	
MOT test number	968327340851	
Result	🗙 Failed	
Fail Offside Front Headlamp not working on dipped beam (1.7.5a)		
Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)		
FailNearside Rear Rear position lamp(s) not working (1.1.A.3b)		
Advice Nearside Front Play in steering rack inner joint(s)		

MOT #9	2016-06-25 11:31
MOT test number	844238254000
Result	✓ Passed

MOT #8	2016-06-25 08:38
MOT test number	211026612580
Result	🗙 Failed
Fail Offside Rear Stop lamp not working (1.2.1b)	
Fail Electronic parking brake warning indicates a malfunction (3.1.7)	
Advice Offside Front Tyre worn close to the legal limit badly worn on outer edge (4	4.1.E.1)
Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	

MOT #7		2015-06-22 11:47
MOT test num	nber	477203075148
Result		✓ Passed
Advice Ne	arside Track rod end ball joint has slight play (2.2.B.1f)	
Advice Fro	ont Brake pad(s) wearing thin (3.5.1g)	





MOT #6	2014-06-25 12:30
MOT test number	727246574130
Result	✓ Passed
MOT #5	2013-06-24 13:27
MOT test number	167895173124
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #4	2012-06-25 10:31
MOT test number	966607772121
Result	✓ Passed
MOT #3	2011-06-23 09:18
MOT test number	637244871129
Result	✓ Passed
MOT #2	2010-10-29 15:34
MOT test number	793732900358
Result	✓ Passed
MOT #1	2009-07-27 12:21
MOT test number	954768309285
Result	✓ Passed





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



YJO6ROU report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-08-15
Last registration	2022-06-23
Complete history	See info



Registration #1	2006-08-15	16 mi
Registration #2	2009-07-27	14.888 mi
Registration #3	2010-10-29	23.147 mi
Registration #4	2011-06-23	25.743 mi
Registration #5	2012-06-25	30.861 mi
Registration #6	2013-06-24	37.896 mi
Registration #7	2014-06-25	45.988 mi
Registration #8	2015-06-22	54.559 mi
Registration #9	2016-06-25	62.068 mi
Registration #10	2017-06-12	68.663 mi
Registration #11	2017-06-12	68.665 mi
Registration #12		11.777 est
Registration #13		11.117 mi
Registration #14		
		11.117 est
Registration #15		01.007 est 01.007 est
-		01.000 est 01.000 est 01.000 est
Registration #15		01.000 est 01.000 est 01.000 est 01.000 est
Registration #15 Registration #16		0.000 es
Registration #15 Registration #16 Registration #17		0.227 es 0.227 es 0.227 es 0.227 es 0.227 es 0.227 es
Registration #15 Registration #16 Registration #17 Registration #18		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2087 mm
Height	1717 mm
Length	4493 mm
Wheel base	2736 mm
Kerb weight	1530 kg
Max. allowed weight	2195 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles	2
Engine number	C045999