





General information

Make	MINI
Model	MINI (R59) COOPER
Colour	White
Year of manufacture	2012
Top speed	127 mph
Gearbox	6 speed Manual

Engine & fuel consumption


Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



Internet history

Entry 1	
Date	2022-02-13
Pictures	2
Listing price	View report





source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-17
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	7
Total items failed	4

MOT #13	2023-12-12 15:40
MOT test number	588989044919
Result	✓ Passed
Next expiry date	2024-12-17

MOT #12	2023-12-12 15:40
MOT test number	202673232823
Result	× Failed
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11	2022-12-08 11:16
MOT test number	203827295831
Result	✓ Passed
MOT #10	2021-12-18 08.24

	2021-12-10-00	.24
MOT tes	2745989724 2745989724	¥10
Result	V Pase	sed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	





MOT #9		2020-11-28 08:26
MOT test number 893721163509		893721163509
Result		✓ Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorate	ed (6.1.7 (g) (i))
MOT #8		2019-12-10 10:25
MOT test	number	190805745490
Result		✓ Passed
Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		

MOT #7	2019-12-09 13:18
MOT test number	166729161458
Result	🗙 Failed
Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 ((g) (i))
Fail Headlamp aim projected beam image is obviously incorrect O/S N/S (4.1.2 (c))	

МОТ #6	2018-12-01 09:55
MOT test number	836643920991
Result	✓ Passed
Advice WET TEST	

МОТ #5	2017-11-18 10:41
MOT test number	612605694917
Result	✓ Passed
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	





MOT #4	2016-12-17 09:38
MOT test number	532048216993
Result	✓ Passed
Advice Oil leak	
MOT #3	2015-12-09 15:17
MOT test number	952944760877
Result	✓ Passed
MOT #2	2015-03-17 10:09
MOT test number	436076075048
Result	✓ Passed
MOT #1	2015-03-17 10:09
MOT test number	177326675022
Result	× Failed
Pass with rectification	Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 17 December 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-01
Last registration	2023-12-12
Complete history	<u>See info</u>



Registration #1	2012-03-01	13 mi
Registration #2	2015-03-17	49.289 mi
Registration #3	2015-12-09	50.364 mi
Registration #4	2016-12-17	52.571 mi
Registration #5	2017-11-18	54.301 mi
Registration #6	2018-12-01	56.457 mi
Registration #7	2019-12-09	57.412 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #9 Registration #10		10.000 est
-		00.000 est 00.000 est 00.000 est
Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1683 mm
Height	1378 mm
Length	3728 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1380 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	2 page 12/12

Number of axles	2
Engine number	A061J151