





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Purple
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-10-09

Pictures 40

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-06
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	6

MOT #11	2023-08-21 13:18
MOT test number	249722869818
Result	✓ Passed
Next expiry date	2024-09-06

MOT #	10	2023-08-21 13:00
MOT te	st number	415330950053
Result		X Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))	
Fail	Offside Front Direction indicator incorrect colour (4.4.3 (a))	

MOT #9	2022-08-31 10:34
MOT test number	285640828412
Result	✓ Passed
Advice Rear Tyre slightly damaged/cracking or perishing Nearside and Offside Minor Offside Registration plate lamp inoperative in the case of multiple lamp.	
(i))	3 of fight 30dfee3 (4.7.1 (b)
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #8

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-09-07 11:09 **MOT** test number 552792271343 Result ✓ Passed **MOT #5** 2019-08-08 09:10 **MOT** test number 507587761770 Result Passed Offside Front Direction indicator slightly discoloured (4.4.3 (a)) **Advice Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MW12RYD

report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Front Headlamp aim too low (4.1.2 (a))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))

MOT test number

951677412446

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice

Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Advice

Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

MOT #2

MOT test number

Result

Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

MOT test number

421466914182

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check





Expires: 6 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



MW12RYD

report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-23
Last registration	2023-08-21
Complete history	See info



Registration #1	2012-07-23	18 mi
Registration #2	2016-07-11	4.550 mi
Registration #3	2017-08-08	29.185 mi
Registration #4	2018-07-24	40.927 mi
Registration #5	2019-08-08	43.004 mi
Registration #6	2019-08-08	43.004 mi
Registration #7	2020-09-07	44.492 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

\neg	imer		(ᅩ
		חשו	ns 1	V 1/1/	reirei	

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	925 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	7232258

CarCheck.co.uk page 12/12