



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AURIS D-4D ACTIVE
Colour	Blue
Year of manufacture	2015
Top speed	109 mph
0 - 60 mph	13.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 2.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-22
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	42
Total items failed	1

MOT #9	2024-01-08 11:12
MOT test number	231589335674
Result	✓ Passed
Next expiry date	2025-01-22
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside repeater lens damaged
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8	2024-01-08 11:12
MOT test number	957089842057
Result	✗ Failed
Pass with rectification	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Advice	Nearside repeater lens damaged
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7**

2023-01-19 15:54

MOT test number

434582790497

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush starting to separate (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush starting to separate (5.3.4 (a) (i))

Advice Collision damage behind front bumper+undertrays and wheel arch liners damaged

MOT #6

2022-01-20 12:38

MOT test number

213363016571

Result

✓ Passed

Minor Front Windscreen wiper blade defective front wiper blades are smearing (3.4 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened brakes discs are scored and corroded on the braking surface (1.1.14 (a) (ii))

MOT #5

2021-01-22 12:30

MOT test number

653699734059

Result

✓ Passed

MOT #4

2019-07-23 14:27

MOT test number

651899353346

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Under trays fitted obscuring some testable items

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Front bumper has accident damage and air con radiator has slight damage and bent, unable to view other items due to under trays etc

**MOT #3** 2019-07-19 11:41**MOT test number** 115568030193**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed deep cut in tread (5.2.3 (d) (ii))**MAJOR** Front Bumper damaged and likely to cause injury when grazed or contacted bumper has sharp edges due to accident damage front (6.1.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Under trays fitted obscuring some testable items**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Front Registration plate insecure (0.1 (a))**DANGEROUS** Offside Rear Tyre has ply or cords exposed deep cut in tread (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Front bumper has accident damage and air con radiator has slight damage and bent , unable to view other items due to under trays etc**DANGEROUS** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2018-07-17 08:33**MOT test number** 114013237635**Result** ✓ Passed**Advice** Non obligatory mirror damaged**Advice** Brake pad(s) wearing thin all inner brake pads appear low (1.1.13 (a) (ii))**Advice** Nearside Front fog light insecure**Minor** Front Windscreen wiper blade defective both (3.4 (b) (i))



MOT #12018-07-13 09:19

MOT test number313324701073

Result		✗ Failed
MAJOR	Nearside Headlamp aim too high (4.1.2 (a))	
Minor	Front Windscreen wiper blade defective both (3.4 (b) (i))	
MAJOR	Nearside Front Side repeater missing (4.4.1 (a) (ii))	
Advice	Non obligatory mirror damaged	
MAJOR	Front Bumper insecure (6.1.4 (a) (i))	
Advice	Brake pad(s) wearing thin all inner brake pads appear low (1.1.13 (a) (ii))	
Advice	Nearside Front fog light insecure	



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
22 January 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	VA15GXR
Plate since	2019-09-29
Current registration	VA15GXR
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-30
Last registration	2024-01-08
Complete history	See info



Registration #1	2015-06-30	27 mi
Registration #2	2018-07-13	29.663 mi
Registration #3	2018-07-17	29.711 mi
Registration #4	2019-07-19	43.261 mi
Registration #5	2019-07-23	43.476 mi
Registration #6	2021-01-22	56.628 mi
Registration #7	2022-05-20	59.277 mi
Registration #8	2022-05-20	59.277 mi
Registration #9	2022-05-20	59.277 mi
Registration #10	2022-05-20	59.277 mi
Registration #11	2022-05-20	59.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1460 mm
Length	4560 mm
Wheel base	2600 mm
Kerb weight	1340 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NDJ239157