





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-15

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



2021-09-13 16:39

MOT history

MOT #11

MOT expiry date	2024-08-09
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #13	2023-08-01 10:30
MOT test number	319587142130
Result	✓ Passed
Next expiry date	2024-08-09
Minor Registration plate lamp inoperative in the case of multiple lamps or ligh	nt sources (4.7.1 (b) (i))

MOT #12	2022-08-10 12:25
MOT test number	568281826905
Result	✓ Passed

MOT test number	967345718424
Result	✓ Passed

MOT #10	2020-08-19 14:34
MOT test number	677143556248
Result	✓ Passed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #9	2019-08-17 08:21
MOT test number	941282910705
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #8 2018-08-07 09:10

MOT test number 142631673663

Result \rightarrow Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #7 2017-08-08 13:17

MOT test number 523047171598

Result
✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #6 2016-08-13 10:58

MOT test number 926416299909

Result
✓ Passed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

(2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2016-08-13 09:49

MOT test number 943330291499

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

CarCheck.co.uk page 4/12



MOT #4 2015-08-15 09:56 **MOT test number** 964845097873 Result ✓ Passed MOT #3 2014-08-16 10:30 659098524297 **MOT test number** Result ✓ Passed MOT #2 2013-08-19 13:44 **MOT test number** 578621433294 Result ✓ Passed MOT #1 2013-05-17 13:15 837887133150 **MOT test number** Result ✓ Passed **Notice** Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	hictor.
UMMIAI	nisiaiv

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-19
Last registration	2023-08-01
Complete history	See info



Registration #1	2010-05-19	20 mi
Registration #2	2013-05-17	32.446 mi
Registration #3	2013-08-19	34.173 mi
Registration #4	2014-08-16	50.040 mi
Registration #5	2015-08-15	64.545 mi
Registration #6	2016-08-13	77.799 mi
Registration #7	2016-08-13	77.799 mi
Registration #8	2017-08-08	91.497 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

AU21080