





report date: 2024-03-29

#### General information

Make	CITROEN
Model	C3 PICASSO PURETECH PLATINUM PICASSO
Colour	White
Year of manufacture	2016
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 4

Date 2023-12-14

Pictures 8









#### source: g3remarketing.co.uk

#### Entry 3

Date	2023-08-03
Pictures	0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 2

Date 2023-08-02	Date	2023-08-02	
-----------------	------	------------	--

Pictures 24

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-01-29
Pictures	1

Listing price <u>View report</u>



source: autoonline.co.uk



report date: 2024-03-29

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2025-03-01
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	12
Total items failed	8

MOT #9		2024-02-27 14:28
MOT test	number	616549936355
Result		✓ Passed
Next expi	ry date	2025-03-01
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2024-02-27 14:28
MOT test number		354136561000
Result		<b>X</b> Failed
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (	e))
Advice Nearside Front	yre worn close to legal limit/worn on edge (5.2.3	(e))
Pass with rectification (ii))	Nearside Windscreen wiper does not clear the v	windscreen effectively (3.4 (b)

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT** #6 2023-02-27 12:27 **MOT** test number 166123586938 Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2022-02-16 15:21
MOT test number	837717367441
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2022-02-16 08:53

**MOT test number** 495441018831

Result X Failed

**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))

Fail Horn not working (7.7 (a))

Fail Nearside Headlamp aim not tested (4.1.2 (b))

**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #3 2021-03-02 15:34

**MOT test number** 162587612473

**Result** ✓ Passed

MOT #2 2020-08-11 14:07

**MOT test number** 494755755111

**Result** ✓ Passed

MOT #1 2019-08-06 10:19

**MOT test number** 884122579590

Result 

Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	المنحطح الطا
UWNEr	nistarv
OWITCH	IIIJCOI Y

,		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN
***************************************		
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

### Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-09-01
Last registration	2024-02-27
Complete history	See info



Registration #1	2016-09-01	29 mi
Registration #2	2019-08-06	29.203 mi
Registration #3	2020-08-11	42.121 mi
Registration #4		0.00 44
Registration #5	2021-03-02	42.122 mi
Registration #6	2022-02-16	49.356 mi
Registration #7	2022-02-16	49.356 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.777 no

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Safety ratings

NCAP rating	***
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

### Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30396110

CarCheck.co.uk page 12/12