



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | SUZUKI |
| Model | IGNIS SZ5 DUALJET |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 105 mph |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 89 BHP |
| Max. torque | 120 Nm at 4.400 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 49.5 mpg |
| Consumption extra urban | 65.6 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 109 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-16 |
| Pictures | 15 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-23 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 2 |
| Total items failed | 0 |

| | |
|------------------|------------------|
| MOT #4 | 2023-09-14 15:58 |
| MOT test number | 815363355179 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-23 |

| | |
|-----------------|--|
| MOT #3 | 2023-09-14 13:11 |
| MOT test number | 847538245222 |
| Result | ✗ Failed |
| MAJOR | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| MAJOR | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |

| | |
|-----------------|------------------|
| MOT #2 | 2022-09-15 14:07 |
| MOT test number | 457907729040 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2021-09-07 15:52 |
| MOT test number | 281749497487 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 305 |
| MOT expiry date | 23 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2018-09-24 |
| Last registration | 2023-09-14 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-09-24 | 25 mi |
| Registration #2 | 2019-09-29 | 25,277 mi |
| Registration #3 | 2021-09-07 | 17.646 mi |
| Registration #4 | 2022-09-29 | 25,277 mi |
| Registration #5 | 2023-09-29 | 25,277 mi |
| Registration #6 | 2023-09-29 | 25,277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 79% |
| Pedestrian | 77% |
| Safety systems | 60% |
| Overall rating | 78% |
| Video | see crash video |



Copyright © 2016 Euro NCAP

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1690 mm |
| Height | 1595 mm |
| Length | 3700 mm |
| Wheel base | 2435 mm |
| Kerb weight | 830 kg |
| Max. allowed weight | 1330 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 32 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | K12C-5393026 |