



MT66YLM


report date: 2024-03-29

General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI EXCLUSIVE
Colour	Grey
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2023-06-03
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #6	2022-06-04 11:05
MOT test number	347203229631
Result	✓ Passed
Next expiry date	2023-06-03
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #5	2021-06-02 12:27
MOT test number	978205866429
Result	✓ Passed

MOT #4	2020-11-06 11:59
MOT test number	130669478637
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #3** 2020-11-06 11:59**MOT test number** 168714445817**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #2** 2019-11-07 16:47**MOT test number** 277689849765**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #1** 2019-11-06 14:48**MOT test number** 967991102633**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Road wheel more than one fixing missing (5.2.1 (a) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Nail in tyre**MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**DANGEROUS** Nearside Front Road wheel more than one fixing missing (5.2.1 (a) (ii))**DANGEROUS** Offside Rear Road wheel more than one fixing missing (5.2.1 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
3 June 2023

Tax status	Valid until 1 June
Days left	33
MOT expiry date	3 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-11-23
Last registration	2022-06-04
Complete history	See info



Registration #1	2016-11-23	27 mi
Registration #2	2019-11-06	33.040 mi
Registration #3	2019-11-07	33.041 mi
Registration #4	2020-11-06	45.956 mi
Registration #5	2022-06-04	45.957 mi
Registration #6	2022-06-04	45.957 mi
Registration #7	2022-06-04	45.957 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1359 kg
Max. allowed weight	2205 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBHD3058661