





### General information

Make	NISSAN
Model	NV200 DCI ACENTA COMBI
Colour	White
Year of manufacture	2013
Top speed	98 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E





# Internet history

Entry 1	
Date	2021-09-28
Pictures	24
Listing price	View report









source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-15
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	25
Total items failed	9

MOT #16	2023-09-06 09:30
MOT test number	978651923585
Result	✓ Passed
Next expiry date	2024-09-15

MOT #15	2023-09-06 09:30
MOT test number	788664363658
Result	× Failed
<b>Pass with rectification</b> all lamps (4.7.1 (b) (ii))	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14	2022-09-07 10:29
MOT test number	348698367309
Result	✓ Passed

MOT #13	2021-09-16 10:48
MOT test number	227073118184
Result	Passed
Advice Central Rear Seat belt buckle slightly damaged seat belt buckle da	maged case (7.1.2 (d))





MOT #12		2021-09-15 08:55
MOT test	number	472120226376
Result		🗙 Failed
MAJOR	Windscreen washer not working windscreen washers inoperative (3.5 (a))	
MAJOR	Offside Front Position lamp not working side lamp inoperative (4.2.1 (a) (ii))	
Advice	Central Rear Seat belt buckle slightly damaged seat belt buckle damaged case (7	.1.2 (d))

MOT #11	2021-04-07 15:26
MOT test number	599165339541
Result	✓ Passed

MOT #10		2021-03-30 09:33
MOT test	number	153696920456
Result		🗙 Failed
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

# MOT #9

MOT te	est n	umb	er
--------	-------	-----	----

MOT test	<b>number</b> 333919	688417
Result	$\checkmark$	Passed
Advice	3 rd row seat belts damaged , however no seats fitted	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Central seat belt buckle button broken but operates,lock unlock ok		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

2020-03-16 15:19



NG13FHX
report date: 2024-03-28

MOT #8	2019-04-09 08:47	
MOT test number	377136414071	
Result	✓ Passed	
Advice N/s washer jet poor		
Advice 3rd row seat belts ripped but no seats fitted		
MOT #7 2019-04-08 15:45		
<b>MOT test number</b> 2977550		

Result		🗙 Failed
MAJOR	Headlamp aim too low n/s (4.1.2 (a))	
Advice	3rd row seat belts ripped but no seats fitted	
MAJOR	Headlamp aim projected beam image is obviously incorrect o/s (4.1.2 (c))	
MAJOR	Headlamp aim not tested o/s (4.1.2 (b))	
Advice	N/s washer jet poor	

MOT #6		2018-04-10 15:30
MOT test i	number	812676634669
Result		✓ Passed
Advice	Rear 3rd seat row seats missing	
Advice	3rd row seat belts damaged , nearside and offside rear	



NG13FHX
report date: 2024-03-28

MOT #5	2018-04-09 10:40
MOT test number	136272917527
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Rear 3rd seat row seats missing	
Fail       Registration plate lamp not working (1.1.C.1d)	
Advice Nearside Rear Tyre worn close to the legal limit worn edge outer (4.1.E.1)	
FailOffside Front coil spring fractured (2.4.C.1a)	
Advice 3rd row seat belts damaged , nearside and offside rear	

MOT #4	2017-04-03 13:22
MOT test number	844490907108
Result	Passed
Advice Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)	

MOT #3	2017-04-03 08:12
MOT test number	176450650723
Result	🗙 Failed
Advice Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)	
Fail       Registration plate lamp not working (1.1.C.1d)	
Fail       Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Headlamp aim too low (1.8)	

MOT #2	2016-03-31 09:32
MOT test number	909914644745
Result	✓ Passed





MOT #1	2016-03-31 09:32	
MOT test number	877922711455	
Result	× Failed	
<b>Pass with rectification</b> (8.2.2)	Nearside Front Windscreen wiper does not clear the windscreen effectively	
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	<b>MOT</b> <b>Expires:</b> 15 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	15 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	L'ESN'
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-07-31
Last registration	2023-09-06
Complete history	See info



2013-07-31	17 mi
2016-03-31	38.192 mi
2016-03-31	38.192 mi
2017-04-03	47.959 mi
2017-04-03	47.959 mi
2018-04-09	58.385 mi
2018-04-10	58.385 mi
2019-04-08	67.767 mi
2019-04-09	67.767 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	11.777 esi
	11.777 mi
	2016-03-31 2016-03-31 2017-04-03 2017-04-03 2018-04-09 2018-04-10 2019-04-08





### Car features

S0225	Air conditionin
\$0295	
50482	
S0501	
\$0566	
S0567	
S0569	

## Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1378 kg
Max. allowed weight	2030 kg

## Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	048784