



report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Black
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 2

Date	2022-02-03
Pictures	33
Listing price	View report



source: yesauto.com

Entry 1

Date	2022-02-01
Pictures	34
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #14 2024-04-02 10:59

MOT test number 553641578103

Result ✓ Passed

Next expiry date 2025-04-01

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))

MOT #13 2023-03-17 12:54

MOT test number 943412521696

Result ✓ Passed

MOT #12 2023-03-17 08:49

MOT test number 125761696584

Result ✗ Failed**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #11 2022-03-30 12:54

MOT test number 607542899253

Result ✓ Passed

**MOT #10** 2021-03-02 14:48**MOT test number** 327384345649**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2020-03-02 10:47**MOT test number** 213374452173**Result** ✓ Passed**MOT #8** 2020-03-02 09:56**MOT test number** 214917399018**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Nail in tyre**MOT #7** 2019-02-22 14:23**MOT test number** 882090438927**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-03-07 10:25**MOT test number** 373871040931**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2017-02-02 16:56**MOT test number** 373986846925**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-02-24 13:26**MOT test number** 334377826571**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre 3mm**Advice** Rear discs light corrosion**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear nail in tyre**MOT #3** 2015-02-28 11:56**MOT test number** 137709455096**Result** ✓ Passed**MOT #2** 2015-02-28 11:56**MOT test number** 858719755070**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2014-02-21 13:48**MOT test number** 277782454091**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
1 April 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	1 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	RV11VOU
Plate since	2024-03-28
Current registration	RV11VOU
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2024-04-02
Complete history	See info



Registration #1	2011-03-01	24 mi
Registration #2	2014-02-21	20.690 mi
Registration #3	2015-02-28	25.252 mi
Registration #4	2016-02-24	31.737 mi
Registration #5	2017-02-02	36.036 mi
Registration #6	2018-03-07	41.998 mi
Registration #7	2019-02-22	46.931 mi
Registration #8	2020-03-02	52.796 mi
Registration #9	2020-03-02	55.277 mi
Registration #10	2020-03-02	55.277 mi
Registration #11	2020-03-02	55.277 mi
Registration #12	2020-03-02	55.277 mi
Registration #13	2020-03-02	55.277 mi
Registration #14	2020-03-02	55.277 mi
Registration #15	2020-03-02	55.277 mi
Registration #16	2020-03-02	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1004814