



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI EXCLUSIVE
Colour	Black
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	8.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 2

Date	2022-06-13
Pictures	41
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-09
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	1

MOT #15	2023-09-01 15:15
MOT test number	159605540533
Result	✓ Passed
Next expiry date	2024-08-31

MOT #14	2023-08-29 10:35
MOT test number	865094288673
Result	✗ Failed
<b>DANGEROUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
<b>Advice</b> Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	

MOT #13	2022-07-07 08:47
MOT test number	855895371124
Result	✓ Passed

**MOT #12** 2022-06-30 12:00**MOT test number** 997582930347**Result** ✗ Failed**DANGEROUS** Offside Front Road wheel more than one fixing missing (5.2.1 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #11** 2021-07-10 07:47**MOT test number** 109300308563**Result** ✓ Passed**MOT #10** 2020-11-04 14:00**MOT test number** 227868091865**Result** ✓ Passed**MOT #9** 2019-11-04 13:43**MOT test number** 214135952394**Result** ✓ Passed

**MOT #8** 2018-11-13 09:06**MOT test number** 819155189986**Result** ✓ Passed**MOT #7** 2018-11-08 10:00**MOT test number** 352640760456**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**MOT #6** 2017-11-06 10:10**MOT test number** 371329114858**Result** ✓ Passed**MOT #5** 2017-11-06 10:10**MOT test number** 622402609335**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2016-11-28 09:16**MOT test number** 510634840490**Result** ✓ Passed**Advice** Offside Rear slight play in anti-roll bar drop link**MOT #3** 2015-11-23 09:19**MOT test number** 553362884222**Result** ✓ Passed**Advice** Camera fitted to front windscreen



MOT #2	2014-11-12 13:05
MOT test number	395376314326
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-11-13 09:30
MOT test number	579647513324
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 <b>VE60BBK</b>
Plate since	2019-09-29
Current registration	 <b>VE60BBK</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-30
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2010-11-30	12 mi
Registration #2	2013-11-13	35.386 mi
Registration #3	2014-11-12	46.644 mi
Registration #4	2015-11-23	57.585 mi
Registration #5	2016-11-28	68.520 mi
Registration #6	2017-11-06	79.011 mi
Registration #7	2017-11-06	79.011 mi
Registration #8	2018-11-08	89.030 mi
Registration #9	2018-11-13	89.159 mi
Registration #10	2019-11-13	99.177 mi
Registration #11	2019-11-13	99.177 mi
Registration #12	2019-11-13	99.177 mi
Registration #13	2019-11-13	99.177 mi
Registration #14	2019-11-13	99.177 mi
Registration #15	2019-11-13	99.177 mi
Registration #16	2019-11-13	99.177 mi
Registration #17	2019-11-13	99.177 mi
Registration #18	2019-11-13	99.177 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1491 mm
Length	4329 mm
Wheel base	2608 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYXR4001295