





report date: 2024-03-28

General information

Make	ТОУОТА
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Silver
Year of manufacture	2015
Top speed	106 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 3.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg
CO2 emission	203 g/km
CO2 label	K



CarCheck.co.uk page 1/12



AU15KYH

report date: 2024-03-28

Internet history

Entry 2

Date 2021-12-03

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-12-01
Pictures	22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-16
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	21
Total items failed	0

MOT #10		2024-02-14 16:25
MOT test	number	462001709807
Result		✓ Passed
Next expi	ry date	2025-02-16
Advice Nearside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))		

MOT #9	2023-02-16 12:51
MOT test number	110099713283
Result	✓ Passed

MOT #8		2023-02-14 17:34
MOT test	number	240980305430
Result		× Failed
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps	s (4.7.1 (b) (ii))
MAJOR	Offside Rear Brake lining(s) contaminated (1.1.13 (b))	
MAJOR	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	

CarCheck.co.uk page 3/12



MOT #7 2022-01-19 16:31

MOT test number 627381110720

MOT #6 2021-02-17 12:47

MOT test number 145863260887

Result

Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material pipes joining load sensing valve (1.1.11 (c))

Advice No emissions detected.

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5 2021-02-03 13:33

MOT test number 643403494441

Result ★ Failed

Advice No emissions detected.

MAJOR Electronic power steering warning lamp indicates a system malfunction (2.6 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material pipes joining load sensing valve (1.1.11 (c))

Advice Nearside Front under wing liner fouling wheel

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4 2019-07-10 15:32

MOT test number 972804036160

CarCheck.co.uk page 4/12



MOT #3 2019-07-03 09:52

MOT test number 839482745969

Result X Failed

MAJOR Nearside Rear Leaf spring fractured (5.3.1 (b) (i))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #2 2018-07-18 11:52

MOT test number 353807037837

Result
✓ Passed

MOT #1 2018-07-18 11:45

MOT test number 684515781218

Result X Failed

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	16 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
	More into /
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-03
Last registration	2024-02-14
Complete history	See info



Registration #1	2015-03-03	21 mi
Registration #2	2018-07-18	96.161 mi
Registration #3	2018-07-18	39.916 mi
Registration #4	2019-07-03	47.440 mi
Registration #5	2019-07-10	47.668 mi
Registration #6	2021-02-03	61.329 mi
Registration #7	2021-02-17	61.329 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10,777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	2135 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KDA716182

CarCheck.co.uk page 12/12