



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT HDI 1000 L1H1 P/V
Colour	White
Year of manufacture	2013
Top speed	90 mph
0 - 60 mph	17.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-17
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-15
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	54
Total items failed	2

MOT #132023-07-31 06:33

MOT test number346675901296

Result✓ Passed

Next expiry date2024-08-15

- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Fluid leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2023-07-28 10:04

**MOT test number**

881871177066

**Result****✗ Failed**

- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Fuel system component leaking (6.1.3 (b) (i))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- MAJOR** Offside Headlamp aim unable to be tested bulb inop (4.1.2 (b))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Fluid leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Nail in tyre

**MOT #11**

2022-08-16 15:18

**MOT test number**

292395892924

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-08-15 10:44

**MOT test number**

824958042084

**Result**

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Horn not working (7.7 (a))
- MAJOR** Offside Front Position lamp missing (4.2.1 (a) (ii))
- MAJOR** Nearside Headlamp aim not tested (4.1.2 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Fluid leak harmful to the environment or a risk to other road users (8.4.1 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2021-08-14 10:06**MOT test number** 896312970812**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-10-01 12:45**MOT test number** 392217496494**Result** ✓ Passed**MOT #7** 2020-09-28 13:37**MOT test number** 727469546334**Result** ✗ Failed**MAJOR** Offside Front Body panel damaged and likely to cause injury (6.2.1 (a) (i))**DANGEROUS** Windscreen in such a condition that visibility through swept area is seriously affected (3.2 (c) (ii))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Windscreen washer not working (3.5 (a))**MOT #6** 2019-10-05 12:38**MOT test number** 194232683488**Result** ✓ Passed**MOT #5** 2018-10-20 12:37**MOT test number** 849618344894**Result** ✓ Passed

**MOT #4** 2018-10-19 17:42**MOT test number** 240479908915**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**MAJOR** Windscreen in an unacceptable condition (3.2 (c) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MAJOR** Windscreen washer not working (3.5 (a))**MOT #3** 2017-10-13 14:43**MOT test number** 923793636565**Result** ✓ Passed**MOT #2** 2016-10-22 13:08**MOT test number** 583242495855**Result** ✓ Passed**MOT #1** 2016-10-22 10:31**MOT test number** 392271604488**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	15 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	5
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-10-30
Last registration	2023-07-31
Complete history	<a href="#">See info</a>



Registration #1	2013-10-30	9 mi
Registration #2	2016-10-22	43.350 mi
Registration #3	2016-10-22	43.350 mi
Registration #4	2017-10-13	67.621 mi
Registration #5	2018-10-19	89.614 mi
Registration #6	2018-10-20	89.614 mi
Registration #7	2019-10-05	108.545 mi
Registration #8	2020-09-28	125.227 mi
Registration #9	2021-09-28	150.000 mi
Registration #10	2022-09-28	150.000 mi
Registration #11	2023-09-28	150.000 mi
Registration #12	2024-09-28	150.000 mi
Registration #13	2025-09-28	150.000 mi
Registration #14	2026-09-28	150.000 mi
Registration #15	2027-09-28	150.000 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	4805 mm
Kerb weight	1780 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	JBDF0027679