



HW59FTX

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-09-11
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	12
Total items failed	14

MOT #13	2020-09-09 15:45
MOT test number	631566605141
Result	✓ Passed
Next expiry date	2021-09-11

MOT #12	2020-09-09 12:36
MOT test number	760806403787
Result	✗ Failed
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11	2019-09-05 17:04
MOT test number	516371109793
Result	✓ Passed

MOT #10	2018-09-10 16:47
MOT test number	650143410499
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge punctured on edge (5.2.3 (e))
Advice	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge has a cut not reaching cords (5.2.3 (e))

**MOT #9** 2018-09-10 08:19**MOT test number** 733035399268**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Rear Exhaust has a major leak of exhaust gases silencer (6.1.2 (a))**Fail** Headlamp aim too high BOTH SIDES (4.1.2 (a))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge has a cut not reaching cords (5.2.3 (e))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge punctured on edge (5.2.3 (e))**MOT #8** 2017-08-14 08:27**MOT test number** 582775959586**Result** ✓ Passed**MOT #7** 2016-09-06 15:40**MOT test number** 776052815182**Result** ✓ Passed**MOT #6** 2015-08-24 10:28**MOT test number** 933537921848**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2014-08-26 12:39**MOT test number** 455638934223**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2013-08-17 10:52**MOT test number** 808509923246**Result** ✓ Passed

Notice Both rear bump stops broken

MOT #3 2013-08-16 12:18**MOT test number** 316528923263**Result** ✗ Failed

Fail Nearside Headlamp not working on main beam (1.7.5a)

Notice Both rear bump stops broken

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #2 2012-08-24 16:36**MOT test number** 445207932259**Result** ✓ Passed



MOT #1		2012-08-24 16:36
MOT test number		417137032280
Result		✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Brake servo vacuum pipe split (3.6.C.1b)	
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)	



Tax & MOT check

✕
Untaxed

Tax expired:
28 November 2020

✕
MOT

Expired:
11 September 2021

Tax status	Expired at 28 November 2020
Days left	1249 days too late
MOT expiry date	11 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	HW59FTX
Plate since	2019-06-29
Current registration	HW59FTX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-11
Last registration	2020-09-09
Complete history	See info



Registration #1	2009-09-11	13 mi
Registration #2	2012-08-24	51.851 mi
Registration #3	2013-08-16	64.348 mi
Registration #4	2013-08-17	64.348 mi
Registration #5	2014-08-26	76.516 mi
Registration #6	2015-08-24	82.999 mi
Registration #7	2016-09-06	95.635 mi
Registration #8	2019-09-09	101.277 mi
Registration #9	2019-09-09	101.277 mi
Registration #10	2019-09-09	101.277 mi
Registration #11	2019-09-09	101.277 mi
Registration #12	2019-09-09	101.277 mi
Registration #13	2019-09-09	101.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629