



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (60BHP)
Colour	Silver
Year of manufacture	2008
Top speed	97 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





## MOT history

MOT expiry date	2025-01-26
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	45
Total items failed	2

MOT #18	2024-01-27 09:05
MOT test number	143121830351
Result	✓ Passed
Next expiry date	2025-01-26
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2024-01-18 14:32
MOT test number	859170153683
Result	✗ Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2023-01-18 11:38
MOT test number	775168315849
Result	✓ Passed

**MOT #15** 2022-01-22 10:25**MOT test number** 690501153017**Result** ✓ Passed

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge bald on inner edge and on wear bars in centre. (5.2.3 (e))

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge bald on inner edge. (5.2.3 (e))

**Advice** Rear silencer corroded.

**Minor** Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14** 2021-01-25 18:17**MOT test number** 910167445162**Result** ✓ Passed**MOT #13** 2021-01-12 07:46**MOT test number** 551146678551**Result** ✗ Failed

**MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**DANGEROUS** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-06-08 14:01

**MOT test number**

536766171857

**Result**

✓ Passed

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside front on inner surfaces (1.1.14 (a) (ii))

**Advice** Oil leak, but not excessive From engine (8.4.1 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11**

2019-04-09 16:01

**MOT test number**

379162687487

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Rear tyre wearing on outer edge

**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Front registration plate cracked

**Advice** Nearside Non obligatory mirror damaged wing mirror

**MOT #10**

2019-04-09 10:25

**MOT test number**

356379982200

**Result**

✗ Failed

- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Nearside Rear tyre wearing on outer edge
- Advice** Nearside Non obligatory mirror damaged wing mirror
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front registration plate cracked
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #9**

2018-04-12 10:15

**MOT test number**

220234316865

**Result**

✓ Passed

- Advice** N/s repeater damaged
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #8**

2017-04-11 15:50

**MOT test number**

160980347174

**Result**

✓ Passed

**MOT #7** 2016-04-08 11:53**MOT test number** 215593200225**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-02-25 11:16**MOT test number** 465606255016**Result** ✓ Passed**MOT #5** 2014-02-21 12:29**MOT test number** 256642754012**Result** ✓ Passed**MOT #4** 2013-02-19 10:48**MOT test number** 616850553089**Result** ✓ Passed**MOT #3** 2012-03-15 09:20**MOT test number** 867015172012**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Advise both rear tyres are wearing unevenly on inner edges

**MOT #2** 2012-03-14 12:29**MOT test number** 628754572086**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Inner Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Advise both rear tyres are wearing unevenly on inner edges**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Inner Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #1** 2011-02-24 09:55**MOT test number** 808945651028**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
26 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	26 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 <b>BV08VGX</b>
Plate since	2019-06-29
Current registration	 <b>BV08VGX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-04
Last registration	2024-01-27
Complete history	<a href="#">See info</a>



Registration #1	2008-03-04	25 mi
Registration #2	2011-02-24	33.133 mi
Registration #3	2012-03-14	43.592 mi
Registration #4	2012-03-15	43.593 mi
Registration #5	2013-02-19	48.844 mi
Registration #6	2014-02-21	54.440 mi
Registration #7	2015-02-25	63.376 mi
Registration #8	2016-04-08	72.342 mi
Registration #9	2017-04-11	80.447 mi
Registration #10	2018-04-12	87.360 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2020-05-20	103.277 mi
Registration #13	2021-05-20	111.277 mi
Registration #14	2022-05-20	119.277 mi
Registration #15	2023-05-20	127.277 mi
Registration #16	2024-01-27	135.277 mi
Registration #17	2024-01-27	143.277 mi
Registration #18	2024-01-27	151.277 mi
Registration #19	2024-01-27	159.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

**Number of axles**

2

**Engine number**

BBM173167