





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TSI 140
Colour	Grey
Year of manufacture	2008
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.7 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2021-08-04


Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-08-13
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	41
Total items failed	10

MOT #18	2023-08-14 10:47
MOT test number	539091221187
Result	✓ Passed
Next expiry date	2024-08-13
Minor Offside Front Outer Drive shaft joint constant velocity boot severely	deteriorated (6.1.7 (g) (i))

MOT #17	2022-07-26 10:29
MOT test number	104118660278
Result	✓ Passed
MOT #16	2021-08-10 12:54
MOT test number	258700619826
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

	2021 00 07 14 04
MOT #15	2021-08-07 14:04
MOT test number	649950248423
Result	X Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #14		2020-10-13 14:16
MOT test	number	291561737199
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13		2019-04-10 09:50
MOT test	number	231681825358
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2018-04-11 10:27
MOT test number	561330293028
Result	✓ Passed
Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #11 2018-04-10 11:44 566900021883 **MOT** test number Result × Failed **Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Fail**

MOT #10

MOT test number

Result

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT test number

838107685714

Result

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail Offside Front Road wheel bead rim badly distorted (4.2.A.1a)

Advice Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT test number

Result

Advice High level brake light not working.

Advice Offside Rear Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

Advice Offside Front Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

MOT test number

Failed

Pass with rectification

Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Offside Rear Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

Advice

High level brake light not working.

Advice


Offside Front Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)

MOT #6		2015-02-27 14:52
MOT test	number	338428355001
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Front tyres worn bald on inner edges	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	High level brake light inop	

CarCheck.co.uk page 6/15



report date: 2024-03-28




MOT #4		2014-02-25 09:08
MOT test	number	955916554083
Result		✓ Passed
Notice	Rear tyres bald on inner edge	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Rear tyres perishing	
Notice	High level brake light dim	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/15



report date: 2024-03-28



MOT #2	201	2-01-16 14:22
MOT test	number 7	76376212032
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	

MOT #1	2011-01-10 13:33
MOT test number	708870811017
Result	✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	





Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-31
Last registration	2023-08-14
Complete history	See info



Registration #1	2008-03-31	17 mi
Registration #2	2011-01-10	16.356 mi
Registration #3	2012-01-16	25.649 mi
Registration #4	2013-01-11	35.642 mi
Registration #5	2014-02-25	45.479 mi
Registration #6	2015-02-27	53.403 mi
Registration #7	2015-02-27	53.403 mi
Registration #8	2016-04-13	56.181 mi
Registration #9	2016-04-13	56.181 mi
Registration #10	2017-04-12	58.875 mi
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 44
Registration #19		11.777 es
Registration #20		11.777 46

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1524 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
	45.45

CarCheck.co.uk page 15/15

Number of seats	7
Number of axles	2
Engine number	BMY 100474