



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	TUCSON T-GDI SPORT EDITION
Colour	Silver
Year of manufacture	2017
Top speed	126 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	175 BHP
Max. torque	265 Nm at 1.500 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-10
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	19
Total items failed	3

MOT #6	2024-03-11 10:38
MOT test number	200880494036
Result	✓ Passed
Next expiry date	2025-03-10

MOT #5	2023-03-08 10:31
MOT test number	961338798545
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #4

2022-03-07 15:16

MOT test number

760829516734

Result

✓ Passed

- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #3** 2022-03-07 10:50**MOT test number** 533717483267**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2021-03-11 13:17**MOT test number** 762324460550**Result** ✓ Passed**MOT #1** 2020-08-25 10:49**MOT test number** 396990413439**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
10 March 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	SK67WRE
Plate since	2019-03-29
Current registration	SK67WRE
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-24
Last registration	2024-03-11
Complete history	See info



Registration #1	2017-09-24	6 mi
Registration #2	2020-08-25	10.754 mi
Registration #3	2020-08-25	10.754 mi
Registration #4	2021-03-11	11.540 mi
Registration #5	2020-08-25	11.540 mi
Registration #6	2020-08-25	11.540 mi
Registration #7	2020-08-25	11.540 mi
Registration #8	2020-08-25	11.540 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1613 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FJHZ974215