





General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С







Internet history

Entry 3	
Date	2023-02-18
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 2	
Date	2022-10-30
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2022-01-19
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	1

MOT #7		2022-10-17 15:46
MOT test	number	966909665325
Result		✓ Passed
Next exp	iry date	2023-10-16
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's v	iew (3.2 (a) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #6	2021-02-24 11:58
MOT test number	602636232547
Result	✓ Passed

MOT #5		2021-02-08 10:43
MOT test	number	529328500321
Result		🗙 Failed
MAJOR	Driver's door cannot be opened from outside the vehicle (6.2.3 (a))	
MAJOR	Offside Headlamp aim too high (4.1.2 (a))	
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR	Nearside Front Seat belt damaged (7.1.2 (b) (i))	
MAJOR	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))	
MAJOR the ingres	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no s of dirt (6.1.7 (g) (ii))	longer prevents





MOT #4	2020-02-12 16:37
MOT test number	857366977765
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in exbush (5.3.4 (a) (i))	xcessive movement Rear
Advice Both front tyres ? Wearing on inner edges	
Advice Offside Rear Nail in tyre	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in bush (5.3.4 (a) (i))	excessive movement Rear
Advice Offside Rear Wheel has slight curb damage	

МОТ #3	2019-02-14 10:28
MOT test number	291978343185
Result	✓ Passed

MOT #2	2019-02-14 10:28
MOT test number	501448137836
Result	× Failed
Pass with rectification	Nearside Front Daytime running lamp lens seriously defective (4.2.1 (b))

MOT #1	2018-05-10 08:50
MOT test number	778126661154
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 30 April 2023	X MOT Expired: 16 October 2023
Tax status	Expired at 30 April 2023
Days left	366 days too late
MOT expiry date	16 October 2023
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	C

Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-08-06
Last registration	2022-10-17
Complete history	See info



Registration #1	2015-08-06	6 mi
Registration #2	2018-05-10	35.985 mi
Registration #3	2019-02-14	42.423 mi
Registration #4	2019-02-14	42.423 mi
Registration #5	2020-02-12	60.822 mi
Registration #6	2021-02-08	70.684 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg
Additional information	
Fuel tank capacity	37
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles	2
Engine number	1121042