



**EX59ZWM**

report date: 2024-03-28

General information

|                     |                   |
|---------------------|-------------------|
| Make                | AUDI              |
| Model               | A4 TDI DPF S LINE |
| Colour              | Black             |
| Year of manufacture | 2009              |
| Top speed           | 143 mph           |
| 0 - 60 mph          | 8.3 seconds       |
| Gearbox             | 6 speed Manual    |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 170 BHP             |
| Max. torque             | 350 Nm at 2.500 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 40.4 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 53.3 mpg            |
| CO2 emission            | 134 g/km            |
| CO2 label               | E                   |







Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-06                  |
| Pictures      | 11                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-11-01 |
| MOT pass rate      | 87 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 2          |
| Total advice items | 20         |
| Total items failed | 1          |

|                  |                  |
|------------------|------------------|
| MOT #15          | 2023-11-02 15:04 |
| MOT test number  | 143329603641     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-11-01       |

|                 |                  |
|-----------------|------------------|
| MOT #14         | 2022-10-19 08:10 |
| MOT test number | 512611482648     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #13         | 2021-10-21 14:30 |
| MOT test number | 339631449208     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #12         | 2021-09-22 11:08  |
| MOT test number | 981763567196  |
| Result          | ✗ Failed  |
| MAJOR           | Nearside Headlamp levelling device inoperative (4.1.5 (a))                    |
| MAJOR           | Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |

**MOT #11** 2021-02-15 13:10**MOT test number** 342999627537**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2020-02-24 15:48**MOT test number** 820438165658**Result** ✓ Passed**Advice** Both rear tyres are badly feathering and may cause road noise**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on the legal limit (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-02-24 15:48**MOT test number** 493237979856**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on the legal limit (5.2.3 (e))**Advice** Both rear tyres are badly feathering and may cause road noise**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Central Exhaust system insecure (6.1.2 (a))**MOT #8** 2019-02-16 15:52**MOT test number** 871831999227**Result** ✓ Passed**MOT #7** 2018-03-05 13:30**MOT test number** 565904732465**Result** ✓ Passed

**MOT #6** 2017-03-04 16:15**MOT test number** 206140635504**Result** ✓ Passed**MOT #5** 2016-03-05 16:42**MOT test number** 525163587871**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-03-09 13:41**MOT test number** 995998565069**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-10-20 10:49**MOT test number** 648003094297**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-09-10 12:20**MOT test number** 899863053285**Result** ✓ Passed



MOT #12012-09-11 10:17

MOT test number926495352223

Result

✓ Passed

NoticeUnder-trays fitted obscuring some underside components

NoticeBrake pad warning light illuminated

AdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)

NoticeEngine covers fitted obscuring some components in the engine bay

AdviceNearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
1 November 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 January           |
| <b>Days left</b>        | 247                             |
| <b>MOT expiry date</b>  | 1 November 2024                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-29 |
| Current registration |            |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2009-09-25               |
| Last registration          | 2023-11-02               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2009-09-25 | 26 mi      |
| Registration #2  | 2012-09-11 | 52.748 mi  |
| Registration #3  | 2013-09-10 | 72.186 mi  |
| Registration #4  | 2014-10-20 | 79.692 mi  |
| Registration #5  | 2015-03-09 | 81.901 mi  |
| Registration #6  | 2016-03-05 | 87.737 mi  |
| Registration #7  | 2017-03-04 | 93.080 mi  |
| Registration #8  | 2018-03-05 | 98.340 mi  |
| Registration #9  | 2019-02-16 | 104.434 mi |
| Registration #10 | 2019-05-29 | 111.277 mi |
| Registration #11 | 2019-05-29 | 111.277 mi |
| Registration #12 | 2019-05-29 | 111.277 mi |
| Registration #13 | 2019-05-29 | 111.277 mi |
| Registration #14 | 2019-05-29 | 111.277 mi |
| Registration #15 | 2019-05-29 | 111.277 mi |
| Registration #16 | 2019-05-29 | 111.277 mi |
| Registration #17 | 2019-05-29 | 111.277 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 93%                             |
| Children       | 84%                             |
| Pedestrian     | 39%                             |
| Safety systems | 71%                             |
| Overall rating | 78%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1826 mm |
| Height              | 1427 mm |
| Length              | 4703 mm |
| Wheel base          | 2808 mm |
| Kerb weight         | 1460 kg |
| Max. allowed weight | 2015 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 65 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 5                |

|                 |            |
|-----------------|------------|
| Number of axles | 2          |
| Engine number   | CAH 074045 |