



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Grey
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-20
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-11-04
<b>MOT pass rate</b>	61 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	34
<b>Total items failed</b>	13

<b>MOT #18</b>	2022-11-05 09:01
----------------	------------------

<b>MOT test number</b>	906279799109
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Next expiry date</b>	2023-11-04
-------------------------	------------

- Minor** Front Brake hose slightly chafed n/s/f, o/s/f. (1.1.12 (b) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coil spring corroded n/s/r, o/s/r, n/s/f. (5.3.1 (b) (i))
- Advice** Exhaust corroded.
- Advice** Front Lower Gearbox mounting defective
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Oil leak.
- Advice** Suspension components corroded.

**MOT #17**

2022-11-02 13:48

**MOT test number**

184568945372

**Result****✗ Failed**

- Advice** Oil leak.
- Advice** Coil spring corroded n/s/r, o/s/r, n/s/f. (5.3.1 (b) (i))
- Advice** Suspension components corroded.
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Brake pedal anti-slip provision missing (1.1.2 (c))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Exhaust corroded.
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Minor** Front Brake hose slightly chafed n/s/f, o/s/f. (1.1.12 (b) (i))
- Advice** Front Lower Gearbox mounting defective
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #16**

2021-10-22 17:07

**MOT test number**

758065495575

**Result****✓ Passed**

- Advice** Exhaust corroded rear box

**MOT #15** 2021-10-20 16:59**MOT test number** 860049525814**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Exhaust corroded rear box**MOT #14** 2021-02-09 08:54**MOT test number** 535742209083**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13** 2021-02-06 13:33**MOT test number** 268688193513**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2020-01-09 16:20**MOT test number** 579089831859**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexy joint (6.1.2 (a))

**MOT #11** 2020-01-09 15:40**MOT test number** 519857435218**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases flexy joint (6.1.2 (a))**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**MOT #10** 2019-02-06 13:47**MOT test number** 931812547507**Result** ✓ Passed**Advice** Exhaust back box corroded**MOT #9** 2019-02-06 11:52**MOT test number** 822550294948**Result** ✗ Failed**Fail** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Exhaust back box corroded**MOT #8** 2018-03-26 09:12**MOT test number** 584953667380**Result** ✓ Passed**Advice** Rear centre seat belt stalk cover missing**Advice** Rear exhaust silencer crodded

**MOT #7** 2018-03-26 08:00**MOT test number** 899124636385**Result** ✗ Failed**Advice** Rear centre seat belt stalk cover missing**Fail** Nearside Front Headlamp aim too low (1.8)**Advice** Rear exhaust silencer crodded**MOT #6** 2017-03-27 10:03**MOT test number** 638392346248**Result** ✓ Passed**MOT #5** 2017-03-27 10:03**MOT test number** 102058940894**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-03-27 12:08**MOT test number** 176736985424**Result** ✓ Passed**Notice** Both rear tyres cracking**Notice** Nail in offside rear tyre**MOT #3** 2014-04-08 11:14**MOT test number** 557968994042**Result** ✓ Passed**Notice** Nail in offside rear tyre



MOT #2	2013-03-20 16:47
MOT test number	166179673062
Result	✓ Passed
<div>Notice</div> Nail in offside rear tyre	

MOT #1	2012-03-07 12:37
MOT test number	739137962074
Result	✓ Passed





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>YH09MVX</b>
Plate since	2019-09-28
Current registration	<b>YH09MVX</b>
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-31
Last registration	2022-11-05
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	15 mi
Registration #2	2012-03-07	23.732 mi
Registration #3	2013-03-20	29.817 mi
Registration #4	2014-04-08	34.982 mi
Registration #5	2015-03-27	38.856 mi
Registration #6	2017-03-27	50.335 mi
Registration #7	2017-03-27	50.335 mi
Registration #8	2018-03-26	56.520 mi
Registration #9	2018-03-26	56.520 mi
Registration #10	2019-02-06	63.628 mi
Registration #11	2019-05-29	65.557 mi
Registration #12	2019-05-29	65.557 mi
Registration #13	2019-05-29	65.557 mi
Registration #14	2019-05-29	65.557 mi
Registration #15	2019-05-29	65.557 mi
Registration #16	2019-05-29	65.557 mi
Registration #17	2019-05-29	65.557 mi
Registration #18	2019-05-29	65.557 mi
Registration #19	2019-05-29	65.557 mi
Registration #20	2019-05-29	65.557 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4723435