



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Black
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-23
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-14
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	23
Total items failed	10

MOT #19	2024-04-15 11:55
MOT test number	752357773307
Result	✓ Passed
Next expiry date	2025-04-14

MOT #18	2024-04-01 10:25
MOT test number	254103341807
Result	✗ Failed
Fail	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps x 2 (4.7.1 (b) (ii))
Fail	Offside Rear Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge scrubbing 205/55/16 (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Rear Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))

MOT #17	2023-04-03 09:06
MOT test number	984770130603
Result	✓ Passed
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone arm bush (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone arm bush (5.3.4 (a) (i))

**MOT #16** 2022-04-01 13:38**MOT test number** 145436836455**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))

MOT #15 2021-03-22 15:30**MOT test number** 346707330465**Result** ✓ Passed**MOT #14** 2020-03-30 15:07**MOT test number** 220401724675**Result** ✓ Passed**MOT #13** 2019-04-15 12:53**MOT test number** 655823734841**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))

Advice Anti-roll bar mounting modified but not seriously weakened slight wear in o/s and n/s front D bushes (5.3.3 (c) (i))

MOT #12 2018-08-29 15:49**MOT test number** 374686661359**Result** ✓ Passed**MOT #11** 2018-08-29 10:11**MOT test number** 143861991196**Result** ✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a))

Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))

Fail Offside Headlamp aim too low (4.1.2 (a))

**MOT #10** 2018-04-06 13:33**MOT test number** 998274093140**Result** ✓ Passed**MOT #9** 2018-04-06 13:33**MOT test number** 961646017640**Result** ✗ Failed

- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Nearside Front coil spring broken (2.4.C.1a)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #8 2017-04-07 10:38**MOT test number** 269970528189**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front coil spring corroded Both (2.4.C.1b)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front exhaust mounting corroded/ broken. Exhaust still fully supported

**MOT #7** 2016-04-06 15:34**MOT test number** 336186725382**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front exhaust bracket broken
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2016-03-31 15:37**MOT test number** 223307128323**Result** ✗ Failed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front exhaust bracket broken

MOT #5 2015-03-30 14:32**MOT test number** 166749985456**Result** ✓ Passed**MOT #4** 2014-04-26 09:38**MOT test number** 219946414442**Result** ✓ Passed



MOT #3	2013-07-08 11:00
MOT test number	249329683165
Result	✓ Passed
MOT #2	2012-07-12 13:09
MOT test number	787094492118
Result	✓ Passed
MOT #1	2011-07-15 09:38
MOT test number	745596791179
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-08
Last registration	2024-04-15
Complete history	See info



Registration #1	2008-09-08	10 mi
Registration #2	2011-07-15	21.266 mi
Registration #3	2012-07-12	25.382 mi
Registration #4	2013-07-08	28.795 mi
Registration #5	2014-04-26	32.051 mi
Registration #6	2015-03-30	35.453 mi
Registration #7	2016-03-31	39.252 mi
Registration #8	2016-04-06	39.404 mi
Registration #9	2017-04-07	42.893 mi
Registration #10	2018-04-06	45.235 mi
Registration #11	2018-04-06	45.235 mi
Registration #12	2019-04-06	45.235 mi
Registration #13	2019-04-06	45.235 mi
Registration #14	2019-04-06	45.235 mi
Registration #15	2019-04-06	45.235 mi
Registration #16	2019-04-06	45.235 mi
Registration #17	2019-04-06	45.235 mi
Registration #18	2019-04-06	45.235 mi
Registration #19	2019-04-06	45.235 mi
Registration #20	2019-04-06	45.235 mi
Registration #21	2019-04-06	45.235 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	131943
---------------	--------