



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE V50
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-28
Pictures	7
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #21	2022-11-10 09:20
MOT test number	999055665037
Result	✓ Passed
Next expiry date	2023-11-09
Advice	Offside & Nearside rear child seats fitted, restricting checking of adult belts.
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Engine EML light on.
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #20	2021-11-03 10:40
MOT test number	375412151832
Result	✓ Passed

MOT #19	2020-12-17 10:19
MOT test number	624964232242
Result	✓ Passed

MOT #18	2020-12-14 15:07
MOT test number	770156556273
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #17	2019-12-03 16:31
MOT test number	436906583859
Result	✓ Passed



MOT #16	2019-12-02 13:50
MOT test number	500984665775
Result	✗ Failed
MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #15	2018-12-05 16:34
MOT test number	367537013489
Result	✓ Passed

MOT #14	2017-12-06 16:06
MOT test number	553908342595
Result	✓ Passed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' cracked along lower edge (8.3.1d)	

MOT #13	2017-12-06 16:06
MOT test number	191853120404
Result	✗ Failed
Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' cracked along lower edge (8.3.1d)	
Pass with rectification Nearside Headlamp aim too high (1.8)	

MOT #12	2016-12-06 16:17
MOT test number	251200203953
Result	✓ Passed

MOT #11	2015-12-07 08:55
MOT test number	193410786632
Result	✓ Passed



MOT #10	2015-12-07 08:55
MOT test number	289711858786
Result	✗ Failed
Pass with rectification Nearside Headlamp aim too low (1.8)	

MOT #9	2014-12-08 11:52
MOT test number	695142544349
Result	✓ Passed
Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2013-12-04 11:31
MOT test number	366908433378
Result	✓ Passed

MOT #7	2013-12-04 11:17
MOT test number	868688833347
Result	✗ Failed
Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	
Fail Nearside Front Headlamp aim too low (1.8)	

MOT #6	2012-11-26 16:17
MOT test number	738391632312
Result	✓ Passed

**MOT #5** 2011-11-28 14:44**MOT test number** 759892831363**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2010-12-06 16:19**MOT test number** 104090140340**Result** ✓ Passed**MOT #3** 2009-12-02 12:08**MOT test number** 412436439442**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Registration plate lamp not working (1.1.5c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-12-02 12:08**MOT test number** 420406039475**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-11-24 14:44**MOT test number** 313549928330**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-08
Last registration	2022-11-10
Complete history	See info



Registration #1	2005-12-08	23 mi
Registration #2	2008-11-24	54.299 mi
Registration #3	2009-12-02	57.394 mi
Registration #4	2010-12-06	61.581 mi
Registration #5	2011-11-28	65.064 mi
Registration #6	2012-11-26	68.206 mi
Registration #7	2013-12-04	71.408 mi
Registration #8	2013-12-04	71.408 mi
Registration #9	2014-12-08	74.932 mi
Registration #10	2015-12-07	77.976 mi
Registration #11	2015-12-07	77.976 mi
Registration #12	2016-12-07	81.020 mi
Registration #13	2017-12-07	84.064 mi
Registration #14	2018-12-07	87.108 mi
Registration #15	2019-12-07	90.152 mi
Registration #16	2020-12-07	93.196 mi
Registration #17	2021-12-07	96.240 mi
Registration #18	2022-11-10	99.284 mi
Registration #19	2022-11-10	99.284 mi
Registration #20	2022-11-10	99.284 mi
Registration #21	2022-11-10	99.284 mi
Registration #22	2022-11-10	99.284 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1402 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	33276