



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Green
Year of manufacture	2005
Top speed	114 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.5 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-23
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-12
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	43
Total items failed	7

MOT #18	2022-04-13 14:10
MOT test number	621212775942
Result	✓ Passed
Next expiry date	2023-04-12
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-01-05 16:40
MOT test number	118537017045
Result	✓ Passed
Advice	Nearside Front fog light inop
Advice	Offside Front top suspension mount slight movement
Advice	Offside Front tyre low inner edge

**MOT #16**

2021-01-05 08:40

MOT test number

420133112591

Result**✗ Failed****Advice** Offside Front tyre low inner edge**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front fog light inop**Advice** Offside Front top suspension mount slight movement**Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**MOT #15**

2019-07-18 10:51

MOT test number

368667762227

Result**✓ Passed****Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front tyre wearing on inner edge**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Centre exhaust pipe corroded**Advice** Both front top suspension mounts have slight movement

**MOT #14**

2019-07-18 09:18

MOT test number

944147656853

Result**✗ Failed****Advice** Centre exhaust pipe corroded**Advice** Both front top suspension mounts have slight movement**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front tyre wearing on inner edge**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
205/55 r16 91v (5.2.3 (d) (i))**MOT #13**

2018-07-12 09:52

MOT test number

780670613150

Result**✓ Passed****Advice** Front Macpherson strut has slight movement at the upper attachment - Both**Advice** Exhaust corroded**Advice** N/S door check strap broken**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**MOT #12**

2017-07-19 10:27

MOT test number

551091403376

Result**✓ Passed****Advice** Front Macpherson strut has slight movement at the upper attachment Both (2.5.A.1c)**Advice** Rear coil spring corroded both (2.4.C.1b)**Advice** N/s door check strap broken

**MOT #11**

2017-07-18 12:58

MOT test number

288817784618

Result**✗ Failed****Advice** N/s door check strap broken**Advice** Front Macpherson strut has slight movement at the upper attachment Both (2.5.A.1c)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear coil spring corroded both (2.4.C.1b)**MOT #10**

2016-07-12 10:35

MOT test number

632720147040

Result**✓ Passed****Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Advice** Inner edge wear on front tyres**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2015-07-20 08:32

MOT test number

888471305295

Result**✓ Passed****MOT #8**

2015-07-18 10:44

MOT test number

297229995170

Result**✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)

**MOT #7** 2014-09-15 11:53**MOT test number** 359618854252**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #6 2013-08-21 15:57**MOT test number** 628103133225**Result** ✓ Passed

- Notice** Nail in nearside rear tyre

MOT #5 2012-09-14 16:01**MOT test number** 508128552213**Result** ✓ Passed

- Notice** Nail in nearside rear tyre

MOT #4 2011-09-02 10:57**MOT test number** 817905441283**Result** ✓ Passed**MOT #3** 2010-09-06 13:58**MOT test number** 320899040409**Result** ✓ Passed



MOT #2	2009-09-17 10:01
MOT test number	101140169292
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-09-18 14:07
MOT test number	952892068276
Result	✓ Passed
Notice	Cut in N/S/F tyre below requirements for reason for rejection



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HJ55XXR
Plate since	2024-03-28
Current registration	 HJ55XXR
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-15
Last registration	2022-04-13
Complete history	See info



Registration #1	2005-09-15	23 mi
Registration #2	2008-09-18	19.895 mi
Registration #3	2009-09-17	22.545 mi
Registration #4	2010-09-06	26.264 mi
Registration #5	2011-09-02	28.569 mi
Registration #6	2012-09-14	30.878 mi
Registration #7	2013-08-21	33.856 mi
Registration #8	2014-09-15	36.169 mi
Registration #9	2015-07-18	37.537 mi
Registration #10	2015-07-20	37.537 mi
Registration #11	2016-07-20	37.537 mi
Registration #12	2017-07-20	37.537 mi
Registration #13	2018-07-20	37.537 mi
Registration #14	2019-07-20	37.537 mi
Registration #15	2020-07-20	37.537 mi
Registration #16	2021-07-20	37.537 mi
Registration #17	2022-04-13	37.537 mi
Registration #18	2023-04-13	37.537 mi
Registration #19	2024-03-28	37.537 mi
Registration #20	2025-03-28	37.537 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#). More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1721 mm
Height	1502 mm
Length	4129 mm
Wheel base	2516 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

AZJ740033