



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D INVINCIBLE
Colour	Blue
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	171 BHP
Max. torque	410 Nm at 1.800 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L






Internet history

Entry 2


Date	2021-09-19
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-05
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-01-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	15

MOT #14	2021-01-26 09:33
MOT test number	978059035347
Result	✓ Passed
Next expiry date	2022-01-27

MOT #13	2020-01-24 09:19
MOT test number	660220399933
Result	✓ Passed

MOT #12	2019-01-28 12:03
MOT test number	601150798171
Result	✓ Passed

MOT #11	2017-03-24 11:38
MOT test number	976720570584
Result	✓ Passed

- Advice** Rear exhaust shield insecure
- Advice** Front wind screen has various stone chips
- Advice** Nearside Front Inner drive shaft boot damaged
- Advice** Offside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

**MOT #10**

2017-03-17 13:51

MOT test number

807153392921

Result**✗ Failed**

- Fail** Rear brake excessively fluctuating (3.7.B.3)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Rear exhaust shield insecure
- Fail** Offside Front Inner Ball joint has excessive play rack end (2.2.B.1f)
- Advice** Front wind screen has various stone chips
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Inner drive shaft boot damaged

MOT #9

2016-03-19 18:38

MOT test number

367853696148

Result**✓ Passed**

- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #8** 2016-03-15 10:59**MOT test number** 812328632663**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Brake pipe excessively corroded rear to front x2 (3.6.B.2c)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Front front brake excessively fluctuating (3.7.B.3)

MOT #7 2015-03-17 16:01**MOT test number** 306136475029**Result** ✓ Passed**MOT #6** 2014-03-24 17:44**MOT test number** 136613784007**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-03-20 11:06**MOT test number** 559259474026**Result** ✗ Failed

- Fail** Nearside Ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Offside Ball joint has excessive play (2.2.B.1f)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-03-19 10:53**MOT test number** 419208073051**Result** ✓ Passed

- Notice** Play in steering rack inner joint(s)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-03-26 14:49**MOT test number** 157406082494**Result** ✓ Passed**MOT #2** 2011-03-31 15:53**MOT test number** 909180291050**Result** ✓ Passed



MOT #1	2010-06-22 14:42
MOT test number	874543770182
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-07-02
Last registration	2021-01-26
Complete history	See info



Registration #1	2007-07-02	6 mi
Registration #2	2010-06-22	52.218 mi
Registration #3	2011-03-31	59.878 mi
Registration #4	2012-03-26	72.339 mi
Registration #5	2013-03-19	84.230 mi
Registration #6	2014-03-20	98.265 mi
Registration #7	2014-03-24	98.386 mi
Registration #8	2015-03-17	113.772 mi
Registration #9	2016-03-15	130.795 mi
Registration #10	2016-03-15	130.795 mi
Registration #11	2016-03-15	130.795 mi
Registration #12	2016-03-15	130.795 mi
Registration #13	2016-03-15	130.795 mi
Registration #14	2016-03-15	130.795 mi
Registration #15	2016-03-15	130.795 mi
Registration #16	2016-03-15	130.795 mi
Registration #17	2016-03-15	130.795 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1617275