



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Silver
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #12	2023-10-19 11:17
MOT test number	199539637150
Result	✓ Passed
Next expiry date	2024-10-26

MOT #11	2022-10-15 09:32
MOT test number	752953357761
Result	✓ Passed

MOT #10	2021-10-01 08:55
MOT test number	404315636345
Result	✓ Passed

MOT #9	2020-10-27 12:44
MOT test number	857286529530
Result	✓ Passed

- Advice** Most of front suspension components corroded
- Advice** Rear Sub-frame corroded but not seriously weakened axle beam (5.3.3 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))

**MOT #8** 2020-10-21 10:57**MOT test number** 606449175017**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner surfaces (1.1.14 (a) (ii))**MAJOR** Stop lamp(s) not working all (4.3.1 (a) (ii))**MAJOR** Front Windscreen washer not working (3.5 (a))**Advice** Rear Sub-frame corroded but not seriously weakened axle beam (5.3.3 (b) (ii))**Advice** Most of front suspension components corroded**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**MOT #7** 2016-01-05 15:37**MOT test number** 712313703094**Result** ✓ Passed**MOT #6** 2016-01-05 13:53**MOT test number** 224175960109**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2015-05-29 10:47**MOT test number** 785299645191**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-05-29 10:47**MOT test number** 476279245165**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-05-30 10:52**MOT test number** 806630854118**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-05-23 10:48**MOT test number** 917993343109**Result** ✓ Passed**Notice** Nearside front and rear tyres slightly perished**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear tyre slightly perished**MOT #1** 2011-06-25 11:22**MOT test number** 189046071194**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-06-23
Last registration	2023-10-19
Complete history	See info



Registration #1	2008-06-23	11 mi
Registration #2	2011-06-25	19.892 mi
Registration #3	2013-05-23	23.171 mi
Registration #4	2014-05-30	25.352 mi
Registration #5	2015-05-29	27.399 mi
Registration #6	2016-01-05	27.890 mi
Registration #7	2016-01-05	27.890 mi
Registration #8	2016-01-05	27.890 mi
Registration #9	2016-01-05	27.890 mi
Registration #10	2016-01-05	27.890 mi
Registration #11	2016-01-05	27.890 mi
Registration #12	2016-01-05	27.890 mi
Registration #13	2016-01-05	27.890 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	19NV4398