



DNI5VMH

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ4
Colour	White
Year of manufacture	2015
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-04
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-26
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #9	2024-04-04 10:45
MOT test number	596840492735
Result	✓ Passed
Next expiry date	2025-04-26

MOT #8	2023-04-13 13:03
MOT test number	412290710178
Result	✓ Passed

MOT #7	2022-04-27 14:21
MOT test number	294044723472
Result	✓ Passed

Advice O/s/r brake disc rusty

MOT #6	2021-03-06 09:23
MOT test number	222267415849
Result	✓ Passed

MOT #5	2020-03-18 10:42
MOT test number	345334581831
Result	✓ Passed

**MOT #4** 2020-03-18 10:31**MOT test number** 959303500068**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #3** 2019-03-19 13:43**MOT test number** 914493691808**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively inner faces (1.1.14 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Parking brake lever travel close to limit**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-04-13 15:33**MOT test number** 399025602776**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened slightly (3.5.1i)



MOT #1	2018-04-11 10:58
MOT test number	151897738715
Result	✗ Failed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened slightly (3.5.1i)
Fail	Nearside Front Headlamp aim beam image kick up to the offside (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	DN15VMH
Plate since	2015-05-29
Current registration	DN15VMH
Plate since	2015-05-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-27
Last registration	2024-04-04
Complete history	See info



Registration #1	2015-04-27	23 mi
Registration #2	2018-04-11	21.675 mi
Registration #3	2018-04-13	21.675 mi
Registration #4	2019-03-19	35.049 mi
Registration #5	2020-03-18	48.912 mi
Registration #6	2020-03-18	48.912 mi
Registration #7	2020-03-18	48.912 mi
Registration #8	2020-03-18	48.912 mi
Registration #9	2020-03-18	48.912 mi
Registration #10	2020-03-18	48.912 mi
Registration #11	2020-03-18	48.912 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1035 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1944567