



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACCESS
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-08-11
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	36
Total items failed	10

MOT #13 2023-08-17 13:51

MOT test number 334496596007

Result ✓ Passed

Next expiry date 2024-09-07

Advice Tyre worn close to legal limit/worn on edge 2x fronts (5.2.3 (e))**Advice** Rear axle corroded

MOT #12 2023-08-16 09:35

MOT test number 454057851186

Result ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))**Advice** Rear axle corroded**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced Holed on offside (6.1.1 (c) (i))**Advice** Tyre worn close to legal limit/worn on edge 2x fronts (5.2.3 (e))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11**

2022-08-19 10:34

MOT test number

868917986471

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-09-08 15:53

MOT test number

565811822682

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear corroded (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #9**

2021-08-31 12:01

MOT test number

374527041328

Result

✗ Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear corroded (1.1.11 (c))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #8** 2020-10-22 11:34**MOT test number** 720417315734**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material 2x front to rears at rear (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Also nail in tyre (5.2.3 (d) (ii))**MOT #7** 2020-10-22 08:38**MOT test number** 176002217716**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
Sidewall cracked to cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Also nail in tyre (5.2.3 (d) (ii))**Advice** Brake pipe corroded, covered in grease or other material 2x front to rears at rear (1.1.11 (c))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**MOT #6** 2019-10-14 12:22**MOT test number** 222355215614**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Slight corrosion on exhaust system**Advice** Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))

**MOT #5** 2019-10-14 10:01**MOT test number** 689353617084**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Slight corrosion on exhaust system
- Advice** Brake pipe corroded, covered in grease or other material both front to rear (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #4 2018-10-16 09:27**MOT test number** 843074116828**Result** ✓ Passed

- Advice** Slight corrosion on both front brake discs
- Advice** Both front to rear brake pipes showing corrosion
- Advice** Exhaust system showing corrosion

MOT #3 2017-10-16 10:39**MOT test number** 590617917920**Result** ✓ Passed

- Advice** Exhaust system showing corrosion

MOT #2 2016-10-17 10:02**MOT test number** 328337085403**Result** ✓ Passed

- Advice** EXHAUST SYSTEM SHOWING SLIGHT CORROSION



MOT #1	2015-10-23 11:08
MOT test number	165481641675
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
7 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-30
Last registration	2023-08-17
Complete history	See info



Registration #1	2012-10-30	7 mi
Registration #2	2015-10-23	19.752 mi
Registration #3	2016-10-17	25.365 mi
Registration #4	2017-10-16	31.079 mi
Registration #5	2018-10-16	37.090 mi
Registration #6	2019-10-14	43.478 mi
Registration #7	2019-10-14	43.478 mi
Registration #8	2020-10-22	50.274 mi
Registration #9	2020-10-22	50.274 mi
Registration #10	2020-10-22	50.274 mi
Registration #11	2020-10-22	50.274 mi
Registration #12	2020-10-22	50.274 mi
Registration #13	2020-10-22	50.274 mi
Registration #14	2020-10-22	50.274 mi
Registration #15	2020-10-22	50.274 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7155098