



**MJ66VHY**

report date: 2024-03-28

General information

Make	BMW
Model	118 118I SPORT
Colour	Grey
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-28
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2024-12-21
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	17
Total items failed	3

MOT #6	2023-12-12 17:19
--------	------------------

MOT test number	512851276926
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-12-21
------------------	------------

- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords wall x3 (5.2.3 (d) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #5**

2023-12-09 12:23

**MOT test number**

982800863336

**Result****✗ Failed**

- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords wall x3 (5.2.3 (d) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Brake performance unable to be tested (1.2.1 (g))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords wall (5.2.3 (d) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4**

2022-12-15 10:49

**MOT test number**

539970232242

**Result****✓ Passed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer Shoulder (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm Also Worn Outer Shoulder (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3**

2021-12-17 13:41

**MOT test number**

115908631510

**Result****✓ Passed**



MOT #2	2020-12-22 09:59
MOT test number	586360927444
Result	✓ Passed

MOT #1	2019-10-29 09:21
MOT test number	732305387293
Result	✓ Passed

**Advice** Rear wiper split



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
21 December 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	21 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-




Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-31
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2016-10-31	14 mi
Registration #2	2019-10-29	18.159 mi
Registration #3	2020-12-22	24.456 mi
Registration #4	2021-12-22	25.277 mi
Registration #5	2022-12-22	25.277 mi
Registration #6	2023-12-12	25.277 mi
Registration #7	2023-12-12	25.277 mi
Registration #8	2023-12-12	25.277 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1300 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	F1901581