





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	KONA PREMIUM
Colour	Black
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date	2021-12-04

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-09-29	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2024-06-29
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #4		2023-06-22 10:53
MOT test i	number	793626545517
Result		✓ Passed
Next expir	ry date	2024-06-29
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords si	dewall (5.2.3 (d) (i))

MOT #3		2023-06-21 08:31
MOT test	number	203252735445
Result		<b>×</b> Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Fluid leak, but not excessive clutch pipe to clutch master (8.4.1 (a) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Fail Ex	chaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords side	wall (5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2		2022-06-30 15:48
MOT test	number	179382832115
Result		✓ Passed
MOT #1		2021-07-26 08:33
MOT test	number	644892569449
Result		<b>✓</b> Passed
Advice	Two rear tyres starting to crack	
Advice	Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front wipers slightly worn	

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	29 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\sim$		h:at	
- CJV	vner	misi	or

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.  More Info >  Plate changes  See in this check if this HYUNDAI had different number plates.		
See in this check if this HYUNDAI had different number plates.		
See in this check if this HYUNDAI had different number plates.		
See in this check if this HYUNDAI had different number plates.	***************************************	
See in this check if this HYUNDAI had different number plates.		
See in this check if this HYUNDAI had different number plates.	***************************************	
See in this check if this HYUNDAI had different number plates.	**********	
See in this check if this HYUNDAI had different number plates.		
See in this check if this HYUNDAI had different number plates.	***************************************	
See in this check if this HYUNDAI had different number plates.		More info >
器 UK	Plate changes	
THE STATE OF THE S	See in this check if this HYUNDAI had different number plates.	
THE STATE OF THE S	Number of plates	,
Plate since	Current registration	NIK NIK
Plate since	Plate since	
More info >	Current registration	OK SIE
More info >	Plate since	
		More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
	,
First mileage registration	2018-07-31
Last registration	2023-06-22
Complete history	See info



Registration #1	2018-07-31	17 mi
Registration #2	2021-07-26	21.874 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	87%
Children	85%
Pedestrian	62%
Safety systems	60%
Overall rating	76%
Video	see crash video



## Dimensions & weight

Width	1800 mm
Height	1565 mm
Length	4165 mm
Wheel base	2600 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

**Engine number** G3LCJU023329