




report date: 2024-03-28

## General information

Make	FORD
Model	FOCUS C-MAX GHIA
Colour	Blue
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption


Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H



Internet history

Entry 1

Date	2021-10-02
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-11
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	47
Total items failed	19

MOT #20	2024-02-12 16:29
MOT test number	282454699122
Result	✓ Passed
Next expiry date	2025-02-11

MOT #19	2024-02-08 12:11
MOT test number	337869262516
Result	✗ Failed
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #18	2023-01-30 12:29
MOT test number	196135001792
Result	✓ Passed

**MOT #17**

2022-02-04 12:24

**MOT test number**

346978547766

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #16**

2022-02-02 13:14

**MOT test number**

846787957126

**Result**

✗ Failed

**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Windscreen washer not working (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))



MOT #152021-01-29 13:34

MOT test number552458413506

Result		✓ Passed
Advice	Offside Front brake hole insecure	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Exhaust mounting defective back box (6.1.2 (a))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

**MOT #14**

2021-01-25 17:27

**MOT test number**

202873095303

**Result****✗ Failed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Macpherson strut damaged and seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front brake hole insecure
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Exhaust mounting defective back box (6.1.2 (a))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #13**

2019-10-02 14:26

**MOT test number**

166295720776

**Result****✓ Passed**

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective back box (6.1.2 (a))

**MOT #12**

2019-09-30 12:41

**MOT test number**

595779911450

**Result**

✗ Failed

**Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Rear Exhaust mounting defective back box (6.1.2 (a))**MOT #11**

2018-03-22 11:36

**MOT test number**

139120825724

**Result**

✓ Passed

**MOT #10**

2017-03-30 10:41

**MOT test number**

854993639280

**Result**

✓ Passed

**MOT #9**

2017-03-30 09:49

**MOT test number**

159239582202

**Result**

✗ Failed

**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #8** 2016-04-01 11:07**MOT test number** 970464078531**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)**Advice** Offside front tyre worn on inner edge**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-04-01 09:13**MOT test number** 895955973549**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside front tyre worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit bald on inner edge (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #6** 2015-04-07 11:20**MOT test number** 766887195096**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #5** 2014-04-10 12:14**MOT test number** 408050104112**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #4** 2013-03-21 16:24**MOT test number** 947920283057**Result** ✓ Passed**Notice** Nsr seat belt not checked child seat fitted**MOT #3** 2012-04-04 10:28**MOT test number** 817585492078**Result** ✓ Passed**MOT #2** 2011-04-06 11:10**MOT test number** 835126191033**Result** ✓ Passed**MOT #1** 2010-04-06 16:36**MOT test number** 162686390418**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
11 February 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-17
Last registration	2024-02-12
Complete history	<a href="#">See info</a>



Registration #1	2007-04-17	15 mi
Registration #2	2010-04-06	34.727 mi
Registration #3	2011-04-06	46.084 mi
Registration #4	2012-04-04	57.373 mi
Registration #5	2013-03-21	67.559 mi
Registration #6	2014-04-10	73.844 mi
Registration #7	2015-04-07	75.553 mi
Registration #8	2016-04-01	77.244 mi
Registration #9	2016-04-01	77.244 mi
Registration #10	2017-03-30	78.392 mi
Registration #11	2017-03-30	78.392 mi
Registration #12	2018-03-29	79.540 mi
Registration #13	2019-03-28	80.688 mi
Registration #14	2020-03-27	81.836 mi
Registration #15	2021-03-26	82.984 mi
Registration #16	2022-03-25	84.132 mi
Registration #17	2023-03-24	85.280 mi
Registration #18	2024-03-23	86.428 mi
Registration #19	2025-03-22	87.576 mi
Registration #20	2026-03-21	88.724 mi
Registration #21	2027-03-20	89.872 mi
Registration #22	2028-03-19	91.020 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1441 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

7K10918