



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SE
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-29
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-17
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	45
Total items failed	17

MOT #19	2022-10-17 14:08
---------	------------------

MOT test number	761730389790
-----------------	--------------

Result	✗ Failed
Fail	Offside Front Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
Advice	Nearside Play in steering rack inner joint(s)
Fail	Headlamp not working on main beam (4.1.1 (a) (ii))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Tyre worn close to legal limit/worn on edge Both rear (5.2.3 (e))
Fail	Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))



MOT #18	2021-09-08 15:34
MOT test number	715254337124
Result	✓ Passed
Advice	Front brake pad warning light on
Advice	Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
Minor	Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #17	2021-09-08 11:04
MOT test number	385809538467
Result	✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor Nearside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

Minor Offside Front Position lamp incorrect colour (4.2.3 (a) (i))

Advice Front brake pad warning light on

Advice Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Coil spring corroded (5.3.1 (b) (i))

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**MOT #16**

2020-09-18 16:11

MOT test number

335215889741

Result

✓ Passed

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Exhaust centre sleeve clamps deteriorated/corroded

Advice

Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

MOT #15

2019-09-06 14:11

MOT test number

165649729849

Result

✓ Passed

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2018-08-13 15:41

MOT test number

913439168691

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13** 2017-08-31 15:34**MOT test number** 439924249024**Result** ✓ Passed**Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #12** 2017-07-06 15:42**MOT test number** 560650477754**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**MOT #11** 2015-12-30 15:29**MOT test number** 511403874856**Result** ✓ Passed**MOT #10** 2015-12-30 12:00**MOT test number** 590057595762**Result** ✗ Failed**Fail** Offside Front Front wheel bearing rough when rotated (2.5.A.2)**MOT #9** 2014-12-09 15:03**MOT test number** 379943244368**Result** ✓ Passed

**MOT #8** 2014-12-09 11:48**MOT test number** 168623144308**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2013-12-03 13:16**MOT test number** 469897133350**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2013-12-03 11:51**MOT test number** 506607233381**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2012-12-15 10:36**MOT test number** 888940252347**Result** ✓ Passed

**MOT #4** 2012-12-15 10:36**MOT test number** 699800752372**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2012-05-16 13:44**MOT test number** 226627132193**Result** ✓ Passed**MOT #2** 2011-07-06 10:02**MOT test number** 765387381110**Result** ✓ Passed**Notice** N/s/front worn inner & wearing outer edges**Notice** O/s/front tyre worn on both edges**MOT #1** 2011-07-06 10:02**MOT test number** 265697881114**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** N/s/front worn inner & wearing outer edges**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** O/s/front tyre worn on both edges



Tax & MOT check

X

Untaxed

Tax expired:
1 September 2022

X

MOT

Expired:
17 September 2022

Tax status	Expired at 1 September
Days left	607 days too late
MOT expiry date	17 September 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DF08EVG
Plate since	2024-03-29
Current registration	 DF08EVG
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-23
Last registration	2022-10-17
Complete history	See info



Registration #1	2008-07-23	9 mi
Registration #2	2011-07-06	47.722 mi
Registration #3	2012-05-16	63.361 mi
Registration #4	2012-12-15	70.351 mi
Registration #5	2013-12-03	82.419 mi
Registration #6	2013-12-03	82.422 mi
Registration #7	2014-12-09	93.014 mi
Registration #8	2014-12-09	93.014 mi
Registration #9	2015-12-30	100.352 mi
Registration #10	2015-12-30	100.352 mi
Registration #11	2016-12-09	100.352 mi
Registration #12	2016-12-09	100.352 mi
Registration #13	2016-12-09	100.352 mi
Registration #14	2016-12-09	100.352 mi
Registration #15	2016-12-09	100.352 mi
Registration #16	2016-12-09	100.352 mi
Registration #17	2016-12-09	100.352 mi
Registration #18	2016-12-09	100.352 mi
Registration #19	2016-12-09	100.352 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807